

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

13

2

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 1 S. R. 11 E.	1-3 K-3 J-3
2. PROPERTY CONTROLLING IN SECTION	T. N. S. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S. R. E. W.	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

REGISTER OF DEEDS
 REGISTER OF DEEDS STAMP AND FILING NUMBER
 MAY 4 11 19 AM 1972
 FILED

I, DONALD A. RATEKIN do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on OCTOBER 25, 1971, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

<u>1-3</u> STAKE & IRON P. POLE S 35.9 24" SOFT MAPLE NE 24.6 TWIN MAPLES NNW 31	<u>K-3</u> STAKE ON STONE S. SIGN ESE 17.57 P. POLE SW 78.25 T. POLE NE 52.72 CL ASPHALT W 3.45	<u>J-3</u> IRON ROD 18" ELM NNE 32.6 FENCE CORNER N 33.6 P. POLE SSE 43.3
--	--	---

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

<u>1-3</u> FOUND 1" IRON	<u>K-3</u> FOUND 5/8" IRON OVER STAKE OVER STONE 2" BELOW ASPHALT	<u>J-3</u> FOUND 1" SQUARE IRON
-----------------------------	--	------------------------------------

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

<u>1-3</u> 1" IRON 14" MAPLE N05°E 58.0' SIGN (7 LANE BRIDGE) N85°E 97.4'	<u>K-3</u> 5/8" IRON S. SIGN S70°E 17.57' P. POLE S45°W 78.25' T. POLE N35°W 52.72' CL ASPHALT WEST 3.45'	<u>J-3</u> 1" SQUARE IRON CL 22" ELM STUMP N10°E 33.3' FENCE CORNER POST N02°W 33.2'
---	--	---

R6227

R6228

R6229

SIGNED BY Donald A. Ratekin DATE 4-18-72

SURVEYOR'S MICHIGAN REGISTRATION NO. 8781

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY _____ DATE _____



SURVEYOR'S MICHIGAN REGISTRATION NO. _____

PAGE 13