ALLEGAN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	For corners in	· ····· S rieden	cinetic of Act 74, Mich. P.A.	¹⁹⁷⁰				
	ALLEGAN (County)	Located In:	Corner Code ≠	₩8 DEC				
	Public Land Survey	T <u>lN</u> <u>Rl3W</u> TR	G-2 TROWBRIDGE					
SUHVEY &		Ţ R						
REMONUMENTAT	Property Controlling 8 _ in Section 8	T R T R T R		1 2 6 2 2 6				
	3. Miscellaneous S _	T R		·				
APR 2 9 1996		T R		Register of Deeds Stamp & File Number				
COMMISSION	4. Lot No, Records 5. Private Claims	ed Pial		A B C D E F G H I J K				
COMMISSION	<u> </u>			2 6 5 1 3 3				
				3				
	I,DONATO R. PITTS IR. in a f	ield survey on	SEPTEMBER 19 19 05	4-7-4-4-4-10-1-1				
	or lines 1 and 2 above were in conformance with regulations and rules have the state of the conformance with regulations and rules have the state of the conformance with regulations and rules have the state of the conformation							
	derivation of Strick High BCHORS	ULIDR UNITED MATER DAMARIA	nont of the lease of the contract of the contr					
	above were in conformance with the ru	I Law and/or that the corner	points mentioned in lines 3, 4 and 9	8 19 20 21 22 23				
	Court of Law; established, re-estable expressed below:	ished, monumented, re-mo	onumented, recovered, found as	┇ ┈╏┈╎┈╎┈╎┈┤┈┤┈┤┈┤┈┤┈┤┈┤┈ ┤				
	NOTE: Not more than 4 corners,	all in the same town and	Tange, may be recorded	10 -30 - 29 - 28 - 27 - 26 - 2				
	on this certificate.		go, may be recorded	12				
	A. Description of original monume	ent and accessons and		13				
	G.L.O SET POST BUTTERNUT 8 S		or subsequent restoration;					
	LYNN 8 N70E 8	3						
	CIRCA 1900 - COUNTY SURV	EYORS NOTES						
	S&S ELM??		(CONTINUI	D ON BACK OF CERTIFICATE)				
	ELM ? 10'							
	1983 - RAYMOND E. MOOR SET 1/2" x 3" P	ED TPE W/CAP						
	B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:							
	FOUND 1/2" x 5' REBAR W/	CAD "D P P 2024	med in restoring or reestablisi					
	FOUND 1/2" x 5' REBAR W/CAP "D.E.E. 29245" S72W 62.66' 1/2" REBAR ON WEST SIDE OF CREEK, COURSE NW			APPROVED REMONUMENTATION CORNER P.A. 345 OF 1990				
	NSON S9.22 CAPPED P	PIPE # 26463 IN CL CREEK, COURSE NW		ALLEGAN COUNTY DATE APPROVED				
	N74E 17.78' 1/2"	9245 IN W OF 8" AS REBAR	SH .	COUNTY REP.				
	SOUTH 50' NE'LY BANK OF STREAM PULLED REBAR AND SET 1/2" x 5' PIPE W/ALLEGAN CO. REMON. RED CAP #23520 TRAVERSED 2548' NORTH AND 2635' SOUTH APPROVED BY THE ALLEGAN CO. REMON PEER GROUP HAVE 13 1995 AND TO ACCOUNT AS A PROPERTY OF A PROPERT							
					AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER.			
	C. Donnardsking of account							
	C. Description of monument for cor 1/2" x 5' PIPE W/ALLEGAN	ner and accessories esta CO. REMON CAP # 2	iblished to perpetuate locating	the position of the corner:				
	1/2 REBAR ON WEST SIDE (OF CREEK, COURSE N	W 679W 69 661	OF ME				
	CAPPED PIPE # 26463 IN CONST 29245 IN W SIDE OF 8	L CREEK, COURSE NW "ASH	' N90W 59.22' S18E 14.71'	THE OF WATCH				
	1/2" REBAR	1	N74E 17.78'	DONALD R				
	NE'LY BANK OF STREAM		SOUTH 50'	PITTS, JR.				
		•		(Surveyor)				
	No. 25e67							
					•	> 11	DOM.	/.
	S	igned by Singular /	1.120	Date 22	Saprangan 1995			
	s	urveyor's Michigan License No	25867					
	$1222005_{ ext{PAGE}}304$	PAGE 1 OF 2	FORM AS	Proyed by Michigan State Board of Land Surveyors, Jan. 28, 797 Revised May 14, 797 Revised Jan., 190				
				and troop beauty 130				

CONTINUED FROM FROMT OF CERTIFICATE

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION.

CENTERLINE 8' CREEK E 1'±
1/2" PIPE W/CAP WEST 350.28 (P.O.T.)
TOP OF BANK WEST 330'±
6" STEEL FENCE POST S 0.3'±
(PARMED DEE) (PAINTED RED)

1994 - DAVID E. ERICKSON
L.C.R.C. LIBER 4, PAGE 390

SET 1/2" x 5' REBAR WITH CAP "DEE 29245"

S72W 62.66' SET 1/2" REBAR ON WEST SIDE OF CREEK, COURSE NW

N90W 59.22' CAPPED PIPE # 26463 IN CL CREEK, COURSE NW

S18E 14.71' SET N&T 29245 IN W OF 8" ASH

N74E 17.78' SET 1/2" REBAR

SOUTH 50' NE'LY BANK OF STREAM