ALLEGAN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 For corners in ALLEGAN (County) Located In: Corner Code ≠# T_IN_R_14W I-4 1. Public Land Survey CHESHIRE _ R _ == R R 2. Property Controlling R in Section R 3. Miscellageous R Register of Deeds Stamp & File Number Property in Sec. В 4. Lot No. _ , Recorded Plat 5. Private Claims . I. DONATO R. PTTTS JR. in a field survey on _______NOVEMBER 17___, 19 95____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established; monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: NOT SET BY GOVERNMENT OLD NOTES - STAKE 30" MAPLE NE 33.5 GUY POLE NE 38.6' ST. SIGN NW 34.3' (CONTINUED ON BACK OF CERTIFICATE) P.P. SE 38.3' P.P. SW 63.8' 24" MAPLE SW 71.4' B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND IRON & STAKE P.P. S55E 38.3' C.L. "X" 8'± & 5'± W PULLED IRON AND SET STANDARD ALLEGAN COUNTY REMON 3/4" x 24" IRON W/RED CAP # 23520 APPROVED BY THE ALLEGAN CO. REMON PEER GROUP ON OCTOBER 10, 1995. THIS POSITION NOT ESTABLISHED BY ORIGINAL GOVERNMENT SURVEYORS. THIS MONUMENT IS ACCEPTED AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE CORNER. APPROVED REMONUMENTATION CORNER
P.A. 345 OF 1990
ALLEGAN COUNTY DATE APPROVED 10-10-95 C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. OF WICHIC STANDARD ALLEGAN CO. REMON 3/4" x 24" IRON W/RED CAP # 23520 NAIL & REMON TAG IN W SIDE GUY POLE, N30°E 42.10' NAIL & REMON TAG IN NE SIDE POWER POLE S55°E 39.28 DONALD R. NAIL & REMON TAG IN NW SIDE GUY POLE S30°W 63.98' PITTS, JR. TOP CENTER OF UNDERGROUND TELE PEDESTAL S20°E 68.59' Land C.L. "X" 8'± N and 5'± W Surveyor 25867 Land

18220005 PAGE 362

SHEET 1 OF 2

BURYEYORS, JAM, 28, 1971 REVISED MAT 14, 1975 REVISED JAM,, 1983 APPROVED BY MICHIGAN STATE BOARD OF LAND S

Date 21 NOVEMBER

(CONTINUED FROM FRONT OF CERTIFICATE) ALLEGAN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

- A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION.
 - 1965 DONALD A. RATEKIN, COUNTY SURVEYOR FOUND IRON IN STAKE NO WITNESSES
 - 1970 DONALO A RATEKIN FOUND IRON IN STAKE NO WITNESSES
 - 1984 RAYMOND E. MOORED UNRECORDED SURVEY NOTES CENTER OF SEC. NO WITNESSES OR NOTATION OF PHYSICAL CORNER
 - 1988 WIGHTMAN MOORED, INC. FOUND STAKE & IRON 40" MAPLE N30E 33.5' GUY POLE N25E 38.7' P.P. S55E 38.3' P.P. S30W 63.9' C.L. "X" 8± N & 5'± W 16" MAPLE S80W 77.7'