MAR 67 2000

n tritë 🚴

## ALLEGAN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

SECTION

FILING REQUIREMENT OF ACT 74, MICH. P. A. 1979 FEB -1 # 8-37

h <del>a,</del> ₹ Es	Mark Carrier	1	Anno An	
FOR CORNERS IN: ALLEGAN COUNTY	LOCATED IN:	CORNER CODE #	Juga G. Sitte	
1. Public Land Survey	T 1N R 14W	M-12	EECICIED AND	
EAST 1/4 CORNER SECTION 36, T.1N., R.14W. CHESHIRE TWP.	T R		ALLEGĂN CODA I Visiti.	
	T R		ALLEGAN COURT FACE.	
	T R	***************************************		
Property Controlling in section	SR		REGISTER OF DEEDS STAMP & FILE NUMBER	
	SR			
Miscellaneous     Property in Sec.	SR		A B C D E F G H I J K L M 2 - 65 - 43 - + 21 - 1	
4. Lot No,Recor	rded Plat	••••••	3	
5. Private Claims		4 7 8 9 10 11 12		
			5	
			7 8 - 1920 - 2122 - 2324 -	
I, Raymond Moored in a field survey on AUG. 5, 1999 do hereby state that under requirments of P.A 74, Michigan P.A of 1970, corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current r			9 10 - 3029 - 2827 - 2625 -	
of survey instructions of the or by a decree of a Court (	e United States Department of the loft Law and/or that the corner points ce with the rules of the Michigan Bo	Interior, Bureau of Land Manag mentioned in the lines 3, 4, ar	gement 12 31 - 32 - 33 - 34 - 35 - 36 •	

Note: Not more than 2 corners, all the same town and range, may be recorded on this cerificate.

- A. Description of original monument and accessories and/or subsequent restoration:
  - 1. GLO NORTH EAST SIDE SEC. 36, T1N R14W 40.00 SET OR SEC POST BEECH 8 N17W 17 BEECH 16 S59W 33

2. KIRK VAN ORDER, ACT 132 SURVEY, 9-16-97
7" CHERRY S.,SE 6.31"
12" ASH NW 20.72"
10" CHERRY W.,SW 23.06"
10" ASH N. 19.96"

3. MOORED LAND SURVEYING, ACT 132 SURVEY, 9-17-97 FOUND 1/2" CAPPED IRON M-12 WEST TO L-12 = N89"53"02"W 2587.20" M-12 NORTH TO M-11 = N 1"04'45" E 2844.87"

APPROVED REMONUMENTATION CORNER P.A. 345 OF 1990

ALLEGAN COUNTY
DATE APPROVED
COUNTY REP.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner;

FOUND 1" IRON (PS#19618) ON OCCUPATION LINE TO WEST PER WITS IN NUMBER (#2) ABOVE. SET STANDARD ALLEGAN COUNTY REMON IRON WITH CAP IN PLACE OF FOUND CORNER.

ACCEPTED POSITION AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER

APPROVED BY ALLEGAN COUNTY REMONUMENTATION PEER GROUP ON \_020. 14, 1999

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET STANDARD 3/4" X 36" ALLEGAN COUNTY REMONUMENTATION IRON WITH CAP.
-NAIL IN W. SIDE 14" ASH N2E 19.99"
-NAIL IN SIDE 10" CHERRY S10E 6.50"
-NAIL IN NW SIDE 12" CHERRY S75W 22.90"
-NAIL IN SW SIDE 14" ASH N25W 20.65"
-FACE OF FENCE POST SOUTH 0.20"

12, T1N., R.13W. NORTH 30.49

Surveyors License No. 26463

