## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in ALLEGAN	-	•		
(County)	Located In:	Corner Code ≠#		
1. Public Land Survey	T _1N _ R _15N _			
	T R T R			
_	T R			
	Ţ R	<del></del>		
	T R T R			
	T R	i	Register of Deeds	Stamp & File Number
4. Lot No, Record				E F G H I J K L I
5. Private Claims			2 5 5	
			3	
			4 - 7 - 8 -	9-10-11-12-
I, GARY C. RILON , in a	field survey onApril_1	19 , 19	5	<del>                                      </del>
do hereby certify that under requireme in lines 1 and 2 above were in confo	rmance with regulations a	nd rules therefore as required	in the " -1817-	16151413-
current manual of survey instructions	of the United States Depa	rtment of the Interior, Bureau of	fland 7	<del></del>
Management or by a decree of a Court above were in conformance with the re	of Law and/or that the corn ules of the Michigan Board	er points mentioned in lines 3, 4 of Land Surveyors or by a Decre	and 5 8 19 20	21 22 23 24
Court of Law; established, re-estat	olished, monumented, re-	monumented, recovered, four	nd as	<del></del>
expressed below:	** * **	_	10 - 30 - 29	272625-
NOTE: Not more than 4 corners on this certificate.	, all in the same town a	nd range, may be recorded	1 1 1	<del>┤╌┝╸╽╶╏╌┩╸</del> ┤╶ <del>╽╸</del> ┪╸
on tine continuate.			12 31 32-	33-34-3536-
A. Description of original monum	nent and accessories an	d/or subsequent restoration	13 <u>                                     </u>	<del></del>
IN 1971 AS FOUND "I" IRON (SEE LAI 19.22' NW OF THE CORNER. B. Description of corner evidence (I-3) Original Post and accessorie RAY MODRED. 1981 TIE TO DAK SADE ( IRON BAR N59W 19.28' (NEAR THE POS	e found and/or method ES NOT RECOVERED. COUNT CHECKS. FOUND OTHER MON	applied in restoring or reest Y Surveyor Stake NOT RECOVER IUMENTATION NEAR THE CORNER (	ablishing corner: RED. FOUND AND ACCEPTED 1 AS FOLLOWS: 1/2* CAPPED I	." ROUND IRON BAR SET BY
C. Description of monument for c (I-3) FOUND 1° ROUND IRON BAR	orner and accessories (	established to perpetuate lo	cating the position of the	corner:
N45E 41.71' PK AND TAG IN WEST FAC	E OF		05 M	icus.
GUY POLE; S60E 59.08' FOUND NAIL	IN		ZZANE.	Garage Contraction of the Contra
SOUTH FACE OF W. DAK; S70W 69.07			GARY	
NAIL AND MICHIGAN DEPARTMENT OF NA		,	BILO	I. M. /
RESOURCES TAG IN NE FACE UTILITY F S4ON 76.31' NAIL IN SE FACE 10° PC	•		SURVE	
NORTH 6' CENTERLINE OF E-W ROAD;	•		No.	
21' CENTERLINE OF N-S ROAD.			2645 1050 (AND	SURVEY
		/	essesso.	1878
Signed by	(1, Sil	دیم	8/1/91	
	2010	Date		
Surveyor's Michigan Licerise No	2645	S	FORM APPROVED BY MICHIGAN STATE BO	DARD OF LAND SURVEYORS, JAN. 28, 1976 REVISED MAY 14, 1975 REVISED JAN., 1983

PAGE 133