

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF—	LOCATED IN—	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	Sec. 2 T. 1 N. R. 15 E. W.	I-2
2. PROPERTY CONTROLLING IN SECTION	T. N. S. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S. R. E. W.	
4. LOT NO. _____	RECORDED PLAT _____	
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER
 1988 NOV -3 AM 8 44
 FILED
 REGISTER OF DEEDS
 INTERIOR DEPARTMENT

I, Randal J. Vuoteveen, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on August 19, 1988, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

I-2: NW corner of "Lake View Park" plat recorded in Liber 5, Page 81 recorded July 23, 1946.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

I-2: Found 1" iron pipe at NW corner of "Lake View Park" plat with round iron East 32.98' and traces of fence buried to East centerline of 52nd Street 8' East.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-2: 1" iron pipe
 sq. spike in S. side 6" red oak E. 22.54'
 sq. spike in SW side 8" white oak S40°E 36.19'
 sq. spike in E side 8" red oak N10°W 17.81'
 sq. spike in NW side 6" red oak S40°W 16.85'
 round iron East 32.98'



SIGNED BY Randal J. Vuoteveen DATE 10.31.88
Randal J. Vuoteveen, Nederveld Associates Surveying Inc.
 SURVEYOR'S MICHIGAN REGISTRATION NO. 28429 (SEAL)

FOR STATE AND UNITED STATES AGENCIES
 SIGNED BY _____ DATE _____
 ATTORNEY AND SIGNED BY _____ DATE _____
 (SEAL)

APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1974, REVISED MAY 14, 1978
 FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1974, REVISED MAY 14, 1978
 ATTACHED SHEET