			•			
COMMINS	LAND CORNER	OUNTY REMONUME R RECORDATION CE ment of Act 74, Mich	RTIFICATE	11114 1114 1114 1114 1114 1114 1114 11	97 JN	η
For comers in				\$50 C	2 11	=
ALLEGAN	Located in:	Corner Code #		重义	2	Π = Π
(County)		•			==	- '-
1. Public Land Survey	T <u>2N</u> R 11 ¹ T R T R	S 1/4 COR SEC 20		\$ 1970 C	1: 27	
2. Property Controlling in Section	S TR S TR S T R	N 1/4 SEC 29 MARTIN TWP.	Regis	ter of Deeds S	temp & Fil	le Number
3. Miscellaneous Property in Sec.	S TR S TR		, A B	CDEF	G H I	J K L F
4. Lot No, Recorded Pla	at		2 6-	-54-	 	
5, Private Claims			4 - 7 - 5	89-	10-	-1112
			6 -10-	17-16	 - 1 5-	14-13-
I, BERYL M. JONES hereby certify that under requirements of the lines 1 and 2 above were in conformance manual of survey instructions of the United or by a decree of a Court of Law and for the conformance with the rules of the Michigal established, re-established, monumented, the NOTE: Not more that 4 corners,	with regulations and rules the States Department of the Intentional that the corner points mentional in Board of Land Surveyors of re-monumented, recovered, for	970, the corner points men herefore as required in the terior, Bureau of Land Man ed in lines 3, 4 and 5 above or by a Decree of a Court found as expressed below:	tioned in 8 19 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	20 21 29 28 28 29 28 28 28 28 28 28 28 28 28 28 28 28 28	27	23 24 24 25 35 35 35 36 36
A. Description of original monument D-9 40.16 CHAINS EAST OF C-9 GL LCR 1" IRON IN MON BOX 4/18/72 I LCR BOAT SPIKE 1/22/74 D. RATER LCR IRON (NO SIZE) 11/8/74 D. RA SURVEY CERTIFICATE 1" IRON 3/6 ACT 132 SURVEY 1" IRON 3/25/80 SURVEY SKETCH NOT IDENTIFIED MCDOUGAL SKETCH SHOWS IRO ASSESSORS PLAT VILLAGE OF MA	LO SET 1/4 SECTION PC D. RATEKIN L.1, PAGE 2 GIN L. 2, PAGE 257 (IS E JEKIN L. 2, PAGE 421 6/72 D. RATEKIN (SAME A D. T/21/89 R. MOORED, N N, NO SIZE, 1918 M/L 9'	OST NO WITNESS'S SH 228 ERRONEOUS) AS 4/18/72 LCR RATE AS 4/18/72 LCR, D. RA' IO WITNESSES WEST OF RAIL	KIN L.1,PAGE 228 TEKIN L.1, PAGE :)		эн
B. Description of corner evidence found a	ind/or method applied in rest	oring or reestablishing com	er:			-
D-9 FOUND 1° IRON IN MON BOX ACCEPTED AS A CAREFUL AND FAITHFI	UL PERPETUATION OF THE	E POSITIN OF THE ORIGIN	VAL CORNER.			

APPROVED REMONUMENTATION CORNER
P.A. 345 OF 1990
ALLEGAN COUNTY
DATE APPROVED
12-10-96
COUNTY REP. Hair L. Van Charles APPROVED BY THE ALLEGAN COUNTY SURVEYORS PEER GROUP ON DECEMBER 10,1996.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-9 REMOVED 1' IRON. REPLACED WITH ALLEGAN CO. REMON MONUMENT

N.55° E SW COR BRICK BUILDING 53.60'

S 69' W POWER POLE 53.00'

N 62' W POWER POLE 53.00'

N 35' W SE COR BLOCK BUILDING 72.20'

S 25° E PK IN R.R. TIE 22,10

Surveyor's Michigan License No.

23514 FORM APPROVED BY MICHIGAN STATE BOARD OF LAUS SURVEYORS, JAN. 28, 1971 Jones SURVEYOR No. 23514

NI OF MICH

Beryl M.

NO IAND SU

\$ 0005_{PAGE} 483