MAR 6 7 2000

SECTION

FIL


ALLEGAN COUNTY REMOI LAND CORNER RECORDATI ING REQUIREMENT OF ACT	ION CERTIFICATE FR	0 FEB	TEE
CORNER CODE #			m =
M- 6.		<u>Ξ</u> φ	0 =
	120	48	
*********			0

RECISTED OF DEEDS STAAD & CUITANIAN			

FOR CORNERS IN: LOCATED IN: **ALLEGAN COUNTY** 1. Public Land Survey T..2.N.. R...11W EAST 14 COENCR, T...... R..... SEC . 13, MARTIN T..... R..... TWP. T...... R..... 2. Property Controlling SISTER OF DEEDS STAMP & FILE NUMBER in section S......R....... 3. Miscellaneous S......R.... В С DE G Н Property in Sec. 2 a 2 4. Lot No......Recorded Plat. 3 4 5. Private Claims.... 5 6 18 i, Raymond Moored in a field survey on AUG. 5,1999 do hereby state that under -117-46 -15-14 7

requirments of P.A 74, Michigan P.A of 1970, corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in the lines 3, 4, and 5 above were in comformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, monumented, recovered, found as expressed below.

Note: Not more than 2 corners, all the same town and range, may be recorded on this certificate.



- A. Description of original monument and accessories and/or subsequent restoration:
 - 1. GLO, CIRCA 1830; NOTES: 40.00 CH'S SET TO QR. SEC. POST WITNESSES: RED OAK 18 S 5 1/2 W 447 RED OAK 10 S 59 W 203

2. HUGH MAC DOUGALL, CO. SURVEYOR; 5-17-1926 FD. E 1/4 CORNER **WELL POINT** OAK 4" SE 39.8' OAK 8" NE 31.5' MAPLE NE 46' 18.5' JOG SOUTH TO W 1/4 POST SECTION 18, T2N, R10W, (ALSO NOTED AS WELL POINT) APPROVED REMONUMENTATION CORNER P.A. 345 OF 1990 ALLEGAN COUNTY

DATE APPROVED OCT. 12, 1899 COUNTY REP. 12, 1899

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FD. 1 1/2" WELL POINT 1.5'+/- DEEP WITH 2 1/2" PIPE ALONG SIDE 26" OAK SE MEASURES 38.4' MAYBE SAME WITNESS TREE. COULD NOT FIND WELL POINT FOR A-6, T.2N., R.10W.

SET 3/4 X 24" ALLEGAN COUNTY REMON IRON WITH CAP INSIDE OF WELL POINT ACCEPTED POSITION AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER.

APPROVED BY ALLEGAN COUNTY REMONUMENTATION PEER GROUP ON OCT. 12, 1999

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: SET 3/4" x 24" ALLEGAN COUNTY REMONUMENTATION IRON WITH CAP INSIDE OF 1 1/2" WELL POINT.

-NAIL & TAG IN E SIDE 20" OAK
-NAIL & TAG IN W SIDE POWER POLE
-NAIL & TAG IN W SIDE POWER POLE
-NAIL & TAG IN W SIDE FENCE POST
-NAIL & TAG IN E SIDE 20" OAK
-NAIL & TAG IN W SIDE POWER POLE
-NAIL

Surveyors License No. 26463



ANTOLESSALIN