JUL 2 0 1999

SECTION	LAND CO	GAN COUNTY REMONUL RNER RECORDATION Quirement of Act 74, M	CERTIFICATE		_
For comers in	·g	dancing it of ver 14' if	HUII. F.J. 1370	- 100 m	97
Allegan				E≅≪	
(County)	Located In:	Corner Code #			五五
 Public Land Survey 	T T3N R R13	K-13 (SW,36)		발로 N	5 %
	TR	Monterey Twp.		***	<u> </u>
	TR			•	- 6
25	T T2N R R13	* K-1 (NW.1)		· S	
Property Controlling in Section	STR	Allegan Twp.			Ţ.
3. Miscellaneous	\$R				
Property in Sec.	\$TR		R	egister of Deeds Stamp	2 Fila Number
	S TR				a - no italiace)
4. Lot No. , Record	ed Plat				
5. Private Claims			_ · 1	ABCDEF	GHIJKL
				5 5	
			3		1-1-1-
1 Basil J. Andress, Jr. in	n a field survey on Decem	ther 6 10 96 dalamin.	_	7 8 9	
requirements of P.A. 74, Michigan	P.A. of 1970, the corner point	s mantinged in lines 1 and 2 a	bove were in 5	7 - 8 - 9 -	+ 10 -+ 11 -+ 12 -
conformance with regulations and	rules therefore as required in t	he current manual of survey is	estructions of the e		
United States Department of the In	iterior, Bureau of Land Manage	ement or by a decree of a Cou	rt of Law and/or 🚽	18 17 16	+ 15 -+ 14 -+ 13 -
that the corner points mentioned in	lines 3, 4 and 5 above were in	r conformance with the rules of	of the Michigan		
Board of Land Surveyors or by a De	ecree of a Court of Law; establ	lished, re-established, manumo	ented.	19 - 20 - 21 -	+ 22 + 23 + 24 -
recovered, found as expressed belo	w:		9		
			10	29 - 28 -	+ 27 -+ 26 -+ 25 -
NOTE: Not more than 2 come	rs, all in the same town and	f range, may be recorded	11		
on this certificate.			12	31 - 32 - 33 -	- 34 35 36 -
			. 13		
A. Description of original monur	nent and accessories and/or	subsequent restoration:			
-GLO				•	
-West S. Side Sec.	36, T3N, R13W	June 7, 187		. Hicks, C.S.	
80.00 Lynn 18 Co	r Sections 35 & 36		ction 1, T2N		Twp.
- North Between Sec	tions 1 & 2		to W 1/4 Co: to SW Cor.	r. 38,84 40.13	
	dary at Post (No Jo		to N 1/4 Cor		
		Cont. East	to NE Cor.	40.20	
CONTINUED ON BACK	OF CERTIFICATE				
				APPROVED REMONU	
B. Description of corner evidence	e found and/or method appli	ied in restoring or reestablis	hing corner:	P.A. 345 OF 1990 ALLEGAN COUNTY	
- Found 3/4" bolt and washer in Monument Box				DATE APPROVED 12-10-96	
Face 32" Sycamore Found 10D Nail N. S:	WNW 71.			COUNTY REP.	of Dan Onto
All of the other pre	ide PP — East 166.: cvious witnesses an	8' e cone due to road	constuction v	roject	
Replaced 3/4" bolt a	and washer with star	ndard Allegon Co. M	onument {3/4'	" x 24" iron	
w/cap and is accepted original corner.	ed as a careful and	faithful perpetuat	ion of the po	osition of the	
-					
Approved by the Alle	egan Co. Remonument:	ation Peer Group De	cember 10, 19	996.	
C. Description of monument for	corner and accessories esta	blished to perpetuate locati	ing the goeitian of	the esener	
Standard Allegan (County Monument in	Monument Box	and are beginners at	the confer.	
					TEN CO
16d & RF	MON. TAG NW SD MON. TAG N SDE		09.12'	(6)	
16d & RE	MON. TAG N SDE	PP S 35 F 201	68' 7.98'	<u> </u>	THE REAL
16d & RE	MON. TAG N SDE	PP S 10 F 250	ነ 72	(*I. <u></u>	MARCHE IN
16d & RE	MON. TAG N SDE	32" SYCAMORE	1 80 W 72	.36'	LIMETOR
IN C/L 2	6th ST (BIT.)			181	10 /5
				A CONTRACTOR	
		1			TEO.
Signed by Sam	() A)	_	~ · · · ·	
Prein &	Newhof		Date 13	- WEC 96	
Surveyor's Michigan License No.	(1	≠ Ĭ			

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983

SHEET 1 OF 2 REVISED OCT., 1985

SURVEY & REMONUMENTATION

USER 0005 PAGE 346

JUL 2 3 1999

SECTION

Description of original monument and accessories and/or subsequent restoration: Continued

- Sept. 28, 29, 30 and Oct. 3, 1878 E.P. Water Main Description Surveyed S½ of Section 36, T3N, R13W, Monterey Township Stone located from roots of Lyn Tree

Meas. North20.08 to Iron

Cont. North 20.08 to Stone Chichester

Meas. East

20.11 to Stake

Cont. East

20.11 to Wagon Tire Stake

Cont. East

20.06 to Stake

Cont. East

20.06 to Original Stake

- Old Notes from Previous County Surveyors

Iron Under Stone

Dist. West to Iron

2654' 1244.2'

Dist. South to Stone Cont. South to Stone

1319.9

- Oct. 23, 1973 Rec. Survey L-842, P-86

D.A. Ratekin, C.S.

E

NE Cor. Section 2, T2N, R13W

Stone

Face 30" Sycamore

N 75° W 71.0'

Nail in N. Side PP

166.681

Face 18" Ash

Centerline Gas Marker

Nail in E. Side PP

N 05° W 240.85' N 05° E 301.50' S 05° E 248.03'

Centerline USGS BM w/List to SE #Y173 1948 East 44.02

- Oct. 30, 1973 D.A. Ratekin, C.S. L.C.R.C. L-002, P-170 T2N, R13W K-1

Found stone w/iron under it Lists identical witnesses as Rec. Survey L-842, P-86

- April 7, 1977

D.A. Ratckin, C.S.

Rec. Survey

L-920, P-162

Lists identical witnesses as Rec. Survey

L-842, P-86 & L.C.R.C. L-002, P-170

SHEET 2 OF 2



1557 0005 PAGE 347

SURVEY & REMONUMENTATION

JJJL 2 6 1999

SECTION