

REMONUMENTATION

APR 25 1995

ALLEGAN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION For corners in

ALLEGAN (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>2N</u> R <u>14W</u>	<u>D-13</u> <u>Valley Twp.</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

1994 DEC 16 AM 9:55
 REGISTER OF DEEDS
 ALLEGAN COUNTY MICHIGAN
Gregory A. Peterson

FILED

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	16	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Donald R. Pitts Jr. in a field survey on August 19, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules theretofore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O.-Set $\frac{1}{4}$ Section Post
 W. Oak 10" N.51°E. 23 Links
 Beech 8" N.82°W. 38 Links


B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No Corner Found
 Set standard Allegan Co. Remon. 3/4"X24" Iron with red cap 23420 Equidistant and on line between C-13 and E-13, T.2N., R.14W.
 Traversed 2604' East & 2605' West
 Approved by Allegan Co. Remon Peer Group on April 12, 1994, and is accepted as a careful and faithful reestablishment of the position of the original corner.

APPROVED REMONUMENTATION CORNER
 P.A. 345 OF 1990
 ALLEGAN COUNTY
 DATE APPROVED 4-12-94
 COUNTY REP. Paul L. Thompson

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Standard Allegan Co. Remon. 3/4"X24" Iron with red cap 23520
 D-1, T.1N., R.14W., Standard Allegan Co. Remon. 3/4"X24" Iron with red cap 23520 East 40.14'
 Nail & Allegan Co. Remon. Tag N.E. side 24" Pine S.55°E. 85.15'
 " " " " " N.W. side 22" Oak S.05°W. 40.15'
 " " " " " S.W. side 18" Cherry N.10°W. 46.75'



Signed by Donald R. Pitts Jr. Date 30 August 1994
 Surveyor's Michigan License No. 25867

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 23, 1973
 REVISED MAY 14, 1975
 REVISED JAN., 1983

LIBER 0005 PAGE 038