APR 2 5 1995

5. Private Claims \_

## ALLEGAN COUNTY REMONIMENTATION LAND CORNER RECORDATION CERTIFICATE A. 1970

	Path delight: Headthyttell and
COMMISSION	Filing Requirement of Act 74, Mich. P

Po	MCOMIGRATA			<i>⊋ 1</i> 25,	2 −π
	ALLEGAN (County)	Located In:	Comer Code ≠#	FEGISIK FEGISIK	_ : =
1.	Public Land Survey	T <u>2N</u> R <u>14W</u> T R T R	E-13 Valley	3.5	" ⊓ ■ □
2.	Property Controlling in Section	T R S T R S T R		75- (	N N
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp &	File Number
4.	Lot No, 1	Recorded Plat		ARCDEFG	налкі

Donald R. Pitts in a field survey on September 10 1994. On hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5. above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a above were in conformative with the fulles of the miningari board of Latin Sulveyors of yaccord as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original	ginal monument and access	iones and/or subsequent	restoration:			
	ost corner Sec. 32 & ine N.78°W. 22 Lin		Circa 1900:	Allegan Co. Sur Iron	veyor	
14" P.	ine N.68°E. 31 Lin	cs		S.W. Cor. House	N.E.	105.51
7-26-88 Alleg	an Co. Surveyor Kirk 1 1/4" Pipe	k L. Van Order		10" W. Oak 24" Elm		58.9' 44.5'
N.W.	Cor. Hse. Foundation	N.E. 119.95'		26" TW B. Oak	S.E.	85.01
S.E.	Cor. Hse. Foundation	N.E. 131.95'		8" Spruce	E.N.E.	65.9'
9* Rea	l Pine	S.W. 68.68'				
Power	Pole	N.W. 60.70				

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

APPROVED REMONUMENTATION CORNER
P.A. 345 OF 1990
ALLEGAN COUNTY Found  $l_4^{\frac{1}{4}}$  Pipe N.W. Cor. House Foundation N.E. 119.95' DATE APPROVED 4-12-94
COUNTY REP. Kink John Chan S.E. Cor. House Foundation N.E. 131.95' S.W. 68.68' N.W. 60.70' Nail in 10" Red Pine P.K. in Power Pole

Pulled Pipe and set Standard Allegan Co. Remon 3/4" X 24" Iron W/Red cap #23520. Approved by the Allegan Co. Remon Peer Group on April 12, 1994, and is accepted as a careful and faithful perpetuation of the position of the original corner.

Traversed 2640' East & 2604' West

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Standard Allegan Co. Remon. 3/4" X 24" Iron W/Red Cap #23520 E-1, T.1N., R.14W. Standard Allegan Co. Remon 3/4" X 24" Iron W/Red Cap #23520

Nail & Allegan Co. Remon Tag in S.W. Side Power Pole N.35°W. 60.69'

" " " " " " " S. Side 14" Spruce N.75°E. 65.86'

" " " " " " S.E. Side 10" Red Pine S.55°W. 68.61' DONALD R. PITTS, JR. Land Surveyor. No.

Date 12 Sept 199

REVISED MAY 14, 1875 REVISED JAH., 1863

· 20 > 2

Surveyor's Michigan License No.  $0005_{\text{PAGE}}$ 

25867 ed Land