ALLEGAN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

MAR.1.6.1991 Fil

S_

s

1. Public Land Survey

2. Property Controlling

in Section

3. Miscellaneous

ling	Requirement	ot	Act	74,	Mich.	P.A.	197
------	-------------	----	-----	-----	-------	------	-----

lley Township
Corner Code ##

2N R 14W N 1/4 Corner _ R _ Section 2 R _ R



Register of Deeds Stamp & File Number

Property in Sec. _ , Recorded Plat 5. Private Claims _

1. Chris Marschall in a lield survey on July 8 19 93 do hereby certifythal under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

AH Grush Survey Set "T" Iron with cap based on 1964 Ratekin Survey 12" Hickory 80.51

N 17° W S 75° E S 22° W 24" Hickory 59.87 18" Hickory 24.93' 28" Hickory s 68° W 66.801

1991 Fd. Capped Iron 22" Hickory SW 25.02' 18" Hickory SSE 32.09' 9" Elm NW 48.73'

Van Ordre Survey

S. Edge Asphalt Rd. S 7.3'

(SEE OTHER SIDE)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found *T* Iron from above witnesses . Held as best evidence of perpetuation of true corner.



C. Description of monument for corner and accessories established to perpetuale locating the position of the corner.

Replaced "T" Iron with standard Allegan County Monument & Cap. Grouted top 3*

(Due to proposed Construction no Standard Monument and cap wer set at this location).

Centerline E-W Bit. Road North 4'±

56.21

Set Nail & Tag W. side 6" Ash N 29°E Set Nail & Tag E. side 18" Walnut N 08°W 52.35

SEE OTHER SIDE Signed by Chris Minachell

July 8,31993

Surveyor's Michigan License No. _____18561

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 AEVISED MAY 14, 1973 REVISED JAN., 1983

LIBER 004 page 247

Page 1062

LIBER 004 PAGE 248

.....

Section A Continued:

Ratekins Files
Iron over Iron
17" Hickory SW 63.7'
14" Hickory S 31.5'
8" Walnut NNW 51.8'

NOTE: Allegan County Remon tag with 16d Duplex Nails were set on October 14, 1993 in line with the cut nails.