For corners in

SECTION

ALLEGAN COUNTY REMONUMENTATION

00 FEB -! En 8: 37

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

yaya a Ciolo


Allegan Located in: Corner Code # 1. Public Land Survey T 2NR 15W A - 10Clyde Twp. 2. Property Controlling in Section 3. Miscellaneous Property in Sec.

Register of Deeds Stamp & File Number

\_, Recorded Plat 4. Lot No. 5. Private Claims

I, Kirk L Van Order in a field survey on Dec 10, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



- A. Description of original monument and accessories and/or subsequent restoration:
  - A 10
  - Not set by GLO (1) (2)
    - Thomas W. Benson, DNR Surveyor info dated Nov. 10, 1995
      Found no evidence of corner on the ground or any occupation
      Established corner midway on line between corners A-9 and A-11 and on the line formed by corners M-9 and M-10, T.2N., R.16W. Allegan Co. Remon. 3/4" x 24" iron with red cap 23520 (continued on back of sheet)
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Fd. standard A.C. Remon. monument and the following accessories:

N86W 80.03', Nail & DNR tag in 14" (now 17") white pine

N44E 53.97', Nail and DNR tag in 10" (now 12") white birch

N13W 138.81', Nail & DNR tag in utility pole (now cut off)

S51W 73.31', (M - 73.11'), Nail & DNR tag in 10" (now 11" scotch) pine

This monument is accepted as the best available evidence of the position of Peer group approved Dec. 28, 1999. the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Standard Allegan Co. Remon. monument (3/4" x 24" steel rod w/red cap #23520) N.86°W. 80.03' Nail & DNR tag in S side 17" white pine 53.97′

N.44°E. Nail & DNR tag in NW side 12" white birch Nail & DNR tag in NE side cut off utility pole N.13°W. 138.81' s.51°W. 73.11' Nail & DNR tag in NW side 11" scotch pine 20.56' South M-10, T.2N., R.16W. Fd. capped 1/2" steel rerod labeled corner witness 15.19' East

Field line to the East Fd. 3/8" x 1.2' steel rod w/pointed & hooked top

Signed by Mild Com Co Surveyor's Michigan License No.

APPROVED REMONUMENTATION CORNER

P.A. 345 OF 1990 ALLEGAN COUNTY

DATE APPROVED OFC 2 COUNTY REP. 1

FORM APPROVED BY MIC Page 1 of 2

Date

VAN ORDER PROFESSIONAL.

South

KIRK L

POFESSIONA

RVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995

(removed)

9' +/-

29.64'

PURKEY &

MAR 07 2000

SECTION

## <u>Section A</u> (continued from Page 1) <u>A-10</u> <u>Clyde Twp, T.2N., R.15W.</u>

N86W 80.03', Nail & tag in 14" pine N44E 53.97', Nail & tag in 10" birch N13W 138.81', Nail & tag in utility pole S51W 73.11', Nail & tag in 10" pine South 20.56' M-10, T.2N., R.16W. South 2645.04', A-11, T.2N., R.15W. North 2645.04', A-9, T.2N., R.15W.