PHRAMEY &

MAR 07 2000

ALLEGAN COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

FEB -1 (2) 8: 37 Filing Requirement of Act 74, Mich. P.A. 1970

SECTION For corners in

<u>Allegan</u> Located In: Corner Code # (County) 1. Public Land Survey T2N R15W A-11 Clyde Twp. 2. Property Controlling in Section 3. Miscellaneous Property in Sec.


yaya a wata

Register of Deeds Stamp & File Number

4. Lot No. _, Recorded Plat 5. Private Claims

Van Orderin a field survey on Dec 10, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A Description of original monument and accessories and/or subsequent restoration:

<u>A-11</u> GLO post established by U.S. Deputy Surveyor L. Lyon in 1831 West between Sections 30 & 31 75.38 to W. boundary 5 links N. of post, where set Post cor. Section 30 & 31 24 links N21E Beech 14 6 links S75E Do 10 (continued on back of sheet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Fd. standard Allegan Co. Remon. monument on range line and the following accessories:
N35E 96.66', Nail & DNR tag 16" (now 18") cherry
S16W 108.15' (M - 108.10'), Nail & DNR tag 24" (now 25") maple
South 3.32' (M - 3.31'), Corner M-11, T.2N., R.16W.
S80W 41.52' (M - 41.56'), Nail & DNR tag 7" (now 11") pine
S70E 47.84' (M - 47.83'), Nail & DNR tag in 10" (now 12") cherry
And is accepted as a careful and faithful perpetuation of the position of accessories:

Peer group approved Dec. 28, 1999.

the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A - 11Standard Allegan Co. Remon. monument (3/4" x 24" steel rod w/red cap

#23520) 96.664 Nail & DNR tag in SE side 18" cherry N35°E Nail & DNR tag in N side 12" cherry Nail & DNR tag in N side 11" pine Nail & DNR tag in W side 25" maple S70°E 47.83' 41.56' **S80°W** S16°W 108.10' Nail & Remon. tag in E side 31" maple s25°W 114.16' 3.31 South M-11, T.2N., R.16W.

Signed by Jung B.

Surveyor's Michigan License No. 23520

APPROVED REMONUMENTATION CORNER P.A. 343 OF 1990

ALLEGAN COUNTY DATE APPROVED 059. 28, 1999 COUNTY REP. 1899

FORM APPROVED BY MICH Page 1 of 2

Date

KIRK VAN ORDER PROFESSIONAL

POFESSIONA

SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995

RF. The server

MAR 07 2000

SECTION

Section A (continued from Page 1) A-11 Clyde Twp., T.2N., R.15W.

George Mitchell survey dated Nov. 10, 1978, Job No. 78-409 shows this corner but does not state what was found 8" pine SW 82.45' 14" cherry E,SE 27.20' NW 54.45' 6" cedar 3.3' M - 11N

Wightman-Moored, Inc. info show 1" iron 3.30' North of corner M-11 (3) (4)

Thomas W. Benson, DNR Surveyor, info dated Jan. 9, 1996 Found 5/8" rerod and none of the above accessories GLO distance to corner M-11, T.2N., R.16W. checked. Replaced 5/8" rerod with standard Allegan Co. Remon. 3/4" x 24" iron with red cap 23520

N35E 96.66', Nail & DNR tag 16" cherry S16W 108.15', Nail & DNR tag 24" maple South 3.32', Corner M-11, T.2N., R.16W. S80W 41.52', Nail & DNR tag 7" pine S70E 47.84', Nail & DNR tag 10" cherry North 2645.04', A-10, T.2N., R.15W. South 2634.67', A-12, T.2N., R.15W.