APR 2 5 1995

00	RRR	A1C	21	MA
4 M 1	וו ועאו		.	

ALLEGAN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

CMMISSIGN	Filing Requirement of Act 74, Mich. P.A. 1970			<i>≥</i> 20 2 2		
For corners in	tuma veda	1	11.68	3 A.L	<u>ξ</u> η	
ALLEGAN (County)	Located In:	Corner Code ##	AN C		, F	
1. Public Land Survèy	T-3N_R -13W TR TR TR	K-3 SE SEC-2 Monterey Twp.	ANH Y HICH	of needs		
	T R T R					
			Register of Da	eds Stamn	& File Number	
	T R					
4. Lot No, Record 5. Private Claims	ded Plat		A B C) P E F	G H 1 J K L	
			4		10-11-12-	
I. BASTI ANDRESS . in a	field survey on	30 JUN 19 94	. 5			
do hereby certify that under requirem in lines 1 and 2 above were in confi current manual of survey instruction	ents of P.A. 74, Michigan P ormance with regulations s of the United States Dep	and rules therefore as required in the artment of the Interior, Bureau of Lan	å 7	_\ ¹ 7\.		
Management or by a decree of a Cour	t of Law and/or that the cor	mer points mentioned in lines 3, 4 and d of Land Surveyors or by a Decree of	3 5 19-	-2021-	-222324-	
Court of Law; established, re-esta expressed below:	ablished, monumented, r	e-monumented, recovered, found a	10 -30	-2925	27 - 26 - 25	
NOTE: Not more than 4 corner on this certificate.	s, all in the same town	and range, may be recorded	12 -31	32 33	34 35 36-	
			13 11			

A. Description of original monument and accessones and/or subsequent restoration:
GLO: NORTH BETWEEN SECTIONS 11 & 12
80.00 SET POST CORNER SECTIONS 1,2,11 & 12 BEECH 6 N 89 E 4LKS HEECH 14 S 72 W 7LKS

> COUNTY SURVEYOR'S OLD NOTES (NO DATE): STAKE & STONE BLACK WALNUT 14" NE 80' SUGAR MAPLE 12" SE 52.2"

> > *CONTINUED ON BACK OF CERTIFICATE*

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FD. 1 1/4" PIPE OVER 1/2" IRON OVER STONE W/ PIECES OF WOODEN STAKE

THIS CORNER IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER.

APPROVED REMONUMENTATION CORNER
P.A. 345 OF 1990
ALLEGAN COUNTY COUNTY REP.

> andress, Jr PROFESSIONAL SURVEYOR

C. Description of monument for corner and accessores established to perpetuate locating the position of the corner.

REPLACED 1 1/4" PIPE, 1/2" IRON & STONE W/ STD. ALLEGAN CO. MON. (3/4' X 24" STEEL PIN W/ CAP)

MOST N'LY COR CONC FND (HSE \$3395) S 40 E 202.27' 16d & REMON TAG N SDE 12" LOCUST N 75 E 218.11' 16d & REMON TAG N SDE 12 LOCUST N 75 E 218.11 16d & REMON TAG NW SDE 20" BOX ELDER N 65 E 79.93' SW COR HSE (WOOD TRIM) N 50 E 93.66' NE COR CONC FND (HSE #2615) N 40 W 171.59' C/L TOP CHAIN LINK FE COR POST N 75 W 142.57' 16d & REMON TAG NW SDE 18" MAPLE S 40 W 107.27'

30075 OFESSION P

Signed by Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SUR

SHEET 1 OF 2

UEE 2005 PAGE 055

CONTINUED FROM FRONT OF CERTIFICATE

A. DESCRIPTION OF THE ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

RECORDED SURVEYS: LIBER-1053, P-70 LIBER-1061, P-275 LIBER-1061, P-289 LIBER-1361, P-155 LIBER-1361, P-157 LIBER-1361, P-159 LIBER-1361, P-161

K.L. VAN ORDER, C.S. 1991-CORNER SHOWN ON SURVEY

L.C.R.C.'S: L-1, P-154 L-1, P-261 L-3, P-325

SONIA MEN CANA CONTRACTOR AND CONTRA

Service of the second