

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____ T. <u>3</u> N. R. <u>15</u> W.		<u>1-12</u> <u>J-12</u>
2. PROPERTY CONTROL LING IN SECTION _____ T. _____ N. S. R. _____ E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION _____ T. _____ N. S. R. _____ E. W.		
4. LOT NO. _____ , RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

FILED
 JAMES B. HARRIS APR 19 1976
 REGISTER OF DEEDS STAMP AND FILING NUMBER

I, DONALD A. RATEKIN do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram-over) were, in a field survey on APRIL 28 1976, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:
1-12 J-12

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
1-12 J-12
 RE-SET 1" IRON ON STRAIGHT SET ON INTERSECTION OF N-S & E-W 1/4 LINES
 LINE AND MIDWAY BETWEEN NW CORNER AND SW CORNER OF SECTION-35

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
1-12 J-12

1" IRON
 PK NAIL N. SIDE TWIN 16" OAKS
 580°W 50.26' N. SIDE
 PK NAIL NW SIDE 12" OAK
 N50°E 50.67'
 PK NAIL N SIDE 14" B. OAK
 N80°E 70.34'
 PK NAIL SW SIDE 12" OAK
 S50°E 78.17'
 IRON IN EXISTING CL. OF ROAD
 (BLAZE MARKS IN ALL TREES)
 SIGNED BY: Donald A. Ratekin DATE 12-28-76

1/2" PIPE (30" LONG) WITH CAP
 12" W. OAK N15°W 8.52'
 TWIN 6" W. OAK N45°W 24.72'
 QUAD 9" CHERRY E TREE S25°W 42.85'
 12" W. OAK W 50.48'
 PK NAIL IN ALL 4 WITNESS TREES. ALSO
 3 BLAZE MARKS IN TREES

SURVEYOR'S MICHIGAN REGISTRATION NO. 8781

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR



SURVEYOR'S MICHIGAN REGISTRATION NO. _____

Form No. ML 1736
 REGISTERED LAND SURVEYORS

LIBED 3 MAR 1976

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 26, 1971
 DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS