APR 2 5 1995

CO	AAA	AIS	2	(1)	V
1 4 4	IVIII	////		. ./ i	v

ALLEGAN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

For corners in		Filing Requirement of Act 74, Mich. P.A. 1970		F= 0,7 == =
_	Allegan (County)	Located In:	Corner Code ≠	DEC :
1.	Public Land Survey	T 3N R 15W T R	F-2 Center Sec. 4 Manlius Twp.	ILED 30 PH 12: C. C. Base CROSPINATIONS
2.	Property Controlling			16
	in Section	S T R	·	
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
4.	Lot No	, Recorded Plat		
5.	Private Claims			
		•		3 4 3 2

I, <u>Kirk Van Order</u>, in a field survey on <u>March 8</u>, 19 <u>94</u>, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- **Corner not set by GLO

 **J.W. Hicks survey drawing dated 11-1-1875 shows section breakdown 2650.56' West of W. 1/4 corner 2651.88' North of S. 1/4 corner 2849.22' South of N. 1/4 corner
- •No LCRC or other surveys found
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

F-2 Set at F-2 F-2 F-2	the intersect N01°44'57"E S01°44'57"W N89°05'27"W S89°05'27"E	2849.19' to F-1 2641.89' to F-3 2646.27' to E-2 2642.40' to G-2	APPROVED REMONUMENTATION CORNER P.A. 345 OF 1990 ALLEGAN COUNTY DATE APPROVED 3-9-94 COUNTY REP. Series Laboration
------------------------------------	---	--	--

This position not established by original government surveyors. This monument is accepted as the best available evidence of the position of the

5491.08' on road traverse 5288.67' off road traverse

Peer Group approved 3-9-94.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

<u>F-2</u>	•	
Set standard Allegan Co. Remon. monument	(3/4" x 24" steel	rod w/red can
#23520)	•	
Nail & Remon. tag in NW side Power Pole	AZ. 12°16'20"	301.89
Nail & Remon. tag in N side Power Pole	- AZ . 95°41'40"	44.46'
Nail & Remon. tag in W side Power Pole	AZ. 173°06'26"	241.49'
Nail & Remon. tag in NW side Power Pole	AZ. 220°12'52"	314.95
Capped iron K.V.O. #23520	N 89°05'27" W	33.00′
•	•	
11/1/1/2/	`	

Surveyor's Michigan License No. _

1857 0005 PAGE 097