APR 2 5 1995

## COMMISSION or corners in

## ALLEGAN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

ر مرح	$G_{3}^{\prime}$	1994	
LEGA!	ž	DEC	T
ALLEGAN COUNTY DEEDS	À	DEC 30	F
F DEE	63	₽	Ш
500		PH 12:	U
	1.		

			_	#≅ ( ८० - ।
_	Allegan <sub>County)</sub>	Located In:	Corner Code =##	30
1.	Public Land Survey	T —3N R 45W T —— R —— T —— B ——	—G-9-NW-Cor— —Sec 27 —Manilus Twp.	C 30 PM 12: 16
2.	Property Controlling	TR STR		
	in Section	S T R		
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
4,	Lot No	Recorded Plat		A B C D E F G H I J K L
5.	Private Claims			

I. John P. Clapp. , in a field survey on \_\_\_\_\_\_December 12, \_\_\_\_ 19\_94 \_\_\_ . do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

d County Surveyor Records

A. Description of original monument and accessories and/or subsequent restoration:

G-9 Gena Land Office	G-9 Recorded in Liber 1	G-9 Old County Survey
Survey Notes 1832	Page 350, July 24, 1972	show "stake" in 1906
Calvin Britain, Surveyor Set Post 18" Pine S46°E 16 links 18" Pine N21°W 26 links	Fd 1 1/2" Pipe 10" W. Oak SE 45. 20" Tw. Oak S 45. 7" W. Oak SW 31.	72' show iron pipe (no da

ld County Surveyor Records iron pipe (no date) 53.7' Oak NE 0ak NW 61.6 Oak SW 32' 8" W. Oak 461 SE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner;

G-9

Found bolt in monument box and accepted it as a careful and faithful perpetuation of the position of the original comer.

No ties remaining.

AFFROVED REMONUMENTATION CORNER
PA. 345 OF 1990
ALLEGAN COUNTY

DATE APPROVED 2-13-COUNTY REP.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set A.C. Remon Iron and Cap in Monument Box

A.C. Remon Tag & Nail in SE Side 14" Twin Oak 35° AZ. 56.86 A.C. Remon Tag & Nail in SW Side 8" Oak 1440 AZ. 70.90 A.C. Remon Tag & Nail in SE Side 15" Twin Oak AZ. 213° 66.91 A.C. Remon Tag & Nail in NE Side 10" Pine 329° AZ. 47.38

Signed by John P. Clapp Surveyor's Michigan License/No.

1994

P CRAJ G

JOHN F

HER 0005 PAGE 098