SECTION

ALLEGAN COUNTY REMONUMENTATION


	LAND CORNER RECORDATION CERTIFICAT
ę	Filing Requirement of Act 74, Mich. P.A. 1970
or corners in	

Allegan Located in: Corner Code # T3N R15W 1. Public Land Survey M-12 Manlius Twp. 2. Property Controlling in Section 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number

, Recorded Plat 5. Private Claims

Order in a field survey on Oct 10, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

M - 12

GLO Original post established by U.S. Government Deputy Surveyor L. (1)Lyon, 1832 Pine 6 N.30W. 18,

W. Oak 7 S.26W. 23 Field survey notes Co. 1937 by unknown surveyor (Book 3, Page 91) (2) 8" B. Oak N.62E. 75.6' 8" Pine 29.47 S.55E.

10" W. Oak S.18E. 90.45' (continued on back of sheet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Fd. capped 1/2" x 24" steel rerod above 1" dia. x 6" long iron pipe. Used witnesses as listed in No. 3 of Part A to find. And is accepted as a careful and faithful perpetuation of the position of the original corner. Removed capped rerod and iron pipe and replaced with a standard Allegan Co. Remon. monument.

Peer group approved Nov. 9, 1999

APPROVED REMONUMENTATION CORNER P.A. 345 OF 1990

ALLEGAN COUNTY DATE APPROVED NOV. 9.
COUNTY REP.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M - 12

Standard Allegan Co. Remon. monument (3/4" x 36" steel rod w/red cap #23520)

Nail & Remon. tag in NW side white pine S35°W 33.90' Nail & Remon. tag in N side 14" white pine Nail & Remon. tag in NW side 13" black oak Nail & Remon. tag in NE side 21" black oak S90°W 31.71′ N45°E 56.83' S65°E 62.62'

Signed by Surveyor's Michigan License PROFESSIONA

Date 12-30-1999.

-

MAR 07 2000

SECTION

Section A (continued from Page 1) M - 12Manlius Twp., T.3N., R.15W.

DNR survey by Gary C. Bilow, April 15, 1991

Fd. 1" iron pipe and set 1/2" rebar w/cap #26453 inside

Set nail & MDNR tag in S face 7" white pine N62E 34.29'

Set nail & MDNR tag in N face 6" white pine N73W 21.14'

Set nail & MDNR tag in SW face 14" red pine N27W 55.20'

Set nail & MDNR tag in S face 8" twin white oak N82W 12.34'

LCRC recorded in Liber 004, Page 137 by Gary C. Bilow, dated Aug. 8,

1991 Same witnesses as in No. 3 above