For corners in				82 0 -	_
Allegan (County)	Locate	ed In:	Corner Code #		
1. Public Land Survey	T3N	_R16W	G-12	8: 50 8: 50	•
	TT		E 1/4 Corner Section 33		
2. Property Controlling in Section	ST	 	Saugatuck Twp.		
3. Miscellaneous	. S T	– :: <u>–––</u>		Register of Deeds Stamp & File Number	
Property in Sec.	S T	R			
I, Steve Lampen do hereby certify that under in lines 1 and 2 above we current manual of survey ins Management or by a decree above were in conformance Court of Law; established	, in requirements of P. re in conformance structions of the Urror of a Court of Law are with the rules of the court of the	n a field survey of A. 74, Michigan with regulation wited States De and/or that the che Michigan Bo	on December 11, 1999, P.A. of 1970, the corner points me s and rules therefore as require partment of the Interior, Bureau o corner points mentioned in lines 3, ard of Land Surveyors or by a Dec re-monumented, recovered, for	2 6 5 4 3 2 3 4 7 8 9 10 11 sentioned ed in the of Land 6 18 17 16 15 14 3 2 3 3 4 4 7 8 9 10 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	12
expressed below:  NOTE: Not more than 4 on this certificat		he same towr	and range, may be recorded	d 10 30 29 28 27 26 2	25
A. Description of origi	inal monument a	nd accessorie	s and/or subsequent restorati		36
G-12		D. Ratek	in - 1973	D. Ratekin - 1973	

Beech 16 S75W
E. Mix - 1857
Stone

GLO - C. Britain - 1831 - Set Post

\$88E

23

A. Gardner - 1880 Stone - No witnesses

Sugar 18

D. Ratekin - 1973
Recorded Survey L-840, P-496
CL Road E 2.0'
NE Corner Tel Outlet N20W 104.14'
Nail N Side Power Pole N80E 69.12'
SW Corner Shed N65E 116.54'

D. Ratekin - 1973
LCRC L-2, P-235
Part "B"
Couldn't Locate Stone
Set 1" Iron at intersection of E-W
% line and East line of Section
using West % post and Center and
NE Corner and SE Corner for line.
Same witnesses as L-840, P-496.

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-12 Found 3/4" Iron
CL Road E 2.0"
NE Corner Tel Outlet N20W 104.14'
Nail in N Side F Pole N80E 69.12'
SW Corner Shed N65E 116.54'

Replaced  $\frac{1}{2}$ " iron with an Allegan County Remonumentation iron and cap and accepted it as careful and faithful perpetuation of the position of the original corner.

Approved by the Allegan County Remonumentation Peer Group on December 14, 1999.

APPROVED REMONUMENTATION CORNER P.A. 345 OF 1990

ALLEGAN COUNTY

DATE APPROVED

DEC. 14, 1899

COUNTY REP. 18 C. 4 Control

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-12 Standard Allegan County Remonumentation %'' x 24" iron with red cap #23520. Azimuth = Michigan State Plane grid direction.

289° 25' Remonumentation tag in S side Power Pole 206.581 83° Remonumentation tag in S side Power Pole 15 ' 69.04' 167° Remonumentation tag in E side 10" Pine 51' 196.86' NW Corner House, Brick 25° 05' 337.15 CL North-South Asphalt Road Pavement 90°

31.1999

Signed by Steven Lampon

Surveyor's Michigan License No. 37279

Date DECEMBER 31,1999