SURVEY & REMONUMENTATION

APR 2 5 1995

COMMISSION

ALLEGAN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

		Filing Requiren	nent of Act 74, Mich.	P.A. 1970	E 30	4 69	
rui	comers in			i	WITHERS I	₽	
	Allegan	Located In:	Corner Code ##		₹ <u>5</u> (贸	Π
	Public Land Survey Property Controlling	T 4N R 14W T R T R T R T R T R T R T R T R T R T R	D-11 S 1/4 Cor. Sec. 29 N 1/4 Cor. Sec. 32		A. C. Leather Ter of diffus NCOUNTY, MICH	30 PH 12: 18	
	in Section	S T R	Overisel Twp.	1			
	Miscellaneous Property in Sec.	S T R . S T R		Regist	er of Deeds Stam	p & File Nur	nber
	rioperty in Sec.	. 3	•				·
4.	Lot No ,	Recorded Plat			ABCDE	: в н і ј	х і
5.	Private Claims					- 	Ť
				2		1:1:1	
				3		 	\dashv
. 1	Kirk Van Order	, in a field survey onMarch	14 10 94	4 بر ا	789	101	1-1-12
		equirements of P.A. 74, Michigan P.A. of					
		in conformance with regulations and		f in the		~ - 151	1-13
		tructions of the United States Departm f a Court of Law and/or that the corner p		UI Land			
		vith the rules of the Michigan Board of L			1 23 27	7777	3— —24
	irt of Law; established, ressed below:	re-established, monumented, re-mo	numented, recovered, for	und as 10			
-						27-1-2	5—1—25
NO	on this certificate	corners, all in the same town and	range, may be recorde	C ''	Y		
	on ans continue			13	1 7 7 7	34-3	5 36
A.	Description of origina	I monument and accessories and/	or subsequent restoration				
	D-11		•				
	•GLO set post	at 40.10 chains Wes	t of E-11.				
	30" Elm		29 links		(Continued	on	
	10" Birch	S33°E	25 links		back of s	heet)	
•		P. 335) 3-11-1982	. 7	a an	226 654		
	Witness iron	om field evidence pip	erine marker	s,se E	326.65′ 50.00′		/
	Witness iron			E	100.00′		
	Witness iron			W	50.00		
2	Witness iron	t evidence found and/or method ap	nlied in restoring or rea	stahishing co	100.00		
٥.	D-11	evidence tobilo and/or metrod ap	plica ili lestolling di lee	ataona mig coi	nici.		
	Fd. tire iron	1 3-14-94 ods 50.00' and 100' W	lest				
	Fd. 1/2" rerod 50.21' East and 100'+/- East in ditch below water John P. Clapp set point by extending a line North from an iron set by M.V.K., South of the center of Section 32 thru the center of said Section as						
	South of the	center of Section	32 thru the	center	of said S	ection	as
	monumented tt	a field division li	ne running to	the East	and west.		
	And is accept	ed as a careful and f	aithful perpet	uation of	f the posit	ion of f	the
	original corr	er.			REMONUMENTAT		
	·				P.A. 345 OF 1990		
	Peer Group ag	proved 8-9-94.	•	DATE APP	ALLEGAN COUNT	94	, _
				COUNTY		Ton Onto	
C .	Description of monum	ent for corner and accessories es	tablished to perpetuate	locating the p	osition of the con	ner:	
	D-11						
	Removed tire	iron and set standared cap #23520)	rd Allegan Co.	Remon.	monument (3/4" x :	36"
	Nail and Remo	n. tag in N side 4"		273°41′0	5" 377	.49'	
		mon witness iron 3/4		93°00'00			
		mon. witness iron 3/		273°00′0			
	NW face ANR p	ipeline pipe marker		176°14'4		.43′	
		ner Section 29		90°00'00	•		
		10111-	, na.	00 00.00	527	1.84'	
•	1	11/1/11/11/11					
	16.1	I hadde	フ .	12-30-	.94		
igr	ned by	1	Date	12 - 30.	17		

18ER 0005 PAGE 151

Section A (continued from Page 1)

D-11

•Holland Engineering, Inc. witness card shows a tire iron was set, JPC 82.
All other witnesses same as LCRC.

•K.V.O. survey shows a 1" pipe found (tire iron)
C/L gravel 45th St.

E 4'+/Ditch line to the East pipeline marker post S,SE 326.65'
Field line to the West

The second secon