



	LAND CO	RNER RECORDATION CERTIF	ICATE						
	Filing Requ	irement of Act 74, Mich. P.A	. 1970		\$. 97			
For corners in									
Allegan	Located In:	6			1100	۷			
ALI EGAN (County)	Lucateo in:	Corner Code #		رد.	3 6	Ě		T	
(Comm)				×.	-:	2		=	
•					20 CO EX	. ~)	.773	
1. Public Land Survey	T4NR14W	F-3 (S 1/4', Sec. 4)		Ξ			,	η	
	TR	Overisel Twp.			XI (*)	、 Ξ	•		1
	T R). E	-	-		
	T R			-	- 3				
2. Property Controlling S	TR				٠,		.,		
in Section S	TR								
			Regis	ster of D	eeds 5	itamo.	8 File	Numbe	P.F
3. Miscellaneous S	<u>TR</u>								-1
Property in Sec. S	T R				-				
d Lat No. Dogge	dad Dies								
4. Lot No, Record 5. Private Claims	ueu Fiat			A B	C D	E F (з н :	JK	LM
				2 6	5	4	3	•	,
•				3		, ,	3	2	1
, Steven Lampen	in a field survey on	November 19, 1996		.			1,0		
	ments of P.A. 74, Michigan P.	A. of 1970, the corner points mentioned		'	8	9	10	11	12
n lines 1 and 2 above were in cor	nformance with regulations a	nd rules therefore as required in the	,	5					
current manual of survey instruction	s of the United States Depart	tment of the Interior, Bureau of Land		6 18 -	17	16	15	14	13
bove were in conformance with the	nto caw and/or that the con Tules of the Michigan Board	ner points mentioned in lines 3, 4, and 5, of Land Surveyors or by a Decree of a		7					
court of Law; established, re-e	stablished, monumented, re	-monumented, recovered, found as	8	19 -	20	21	22	23	24
expressed below:		,,	,	, L					
-•		•	1		200	20	77	ا بر	05
OTE: Not more than 4 come	ers, all in the same town	and range, may be recorded		1	29	28	27	26	25
on this certificate.	•		1				٠. ١		
Donotinting of acidinal and			1:	2 31	32	33	34	35	36
. Description of onginal mo	onument and accessories	and/or subsequent restoration:	- 3						
LO - Britain - 1832		at County Surveyors Office from G-3		umers P		30., 1	968		
ritain 1832		gn SW 15.2'	1" 1	on Rate	Kin				
et 1/4 section post		t NE 33.2'		et sign	W-15	21			
ugar 12" N 68" E 25'		block building NW 111.2		a NE 30		-			
o 10" 8 58" W 24'				rete Bl		da NW	111.2		
0.75	_								
976 Survey Consumers Power ound pipe from witnesses		No							
oad sign S 87th W 15.35'		Moored Survey 1990							
elephone riser box 8 45°±;		W from SE corner							
E corner block building NH		1990							
	E-3 W 264								
•	G-3 E 263								
 Description of corner evid 	lence found and/or metho	od applied in restoring or reestabl	ishing co	rner:					
ound 1/2" bar in monument	box						·		
E corner block building NW									
ound 1/2" iron in monument	box is accepted as a	careful and faithful perpetu	uation o	f the o	rigin:	l cor	ner.		
eplaced 1/2" iron with 3/"	x24" Allegan County R	emon. and Remon. cap.							
		<u>-</u>	-						
pproved by Allegan County	autochors seet Group	on Movember 26, 1996.							
			APPRO	VED REM	ONUM	ENTATI	ON COR	NER	
				P./	1. 345 O	F 1990			
				ALL	EGAN C	YTYUO	at.		
			DATE.	APPROVE	D	- 276-	70		
		i	COUN	TY REP	Kir.	1.1/5	rind	كسيده	
		•							
. Description of monument	for corner and accessori	es established to perpetuate loca	tina tha i	ancition.	af +ba				
-3		ar advanced to perpensive too	ting tric i	110011204	YOU WILL	u _{lle}			
/4"x24" Allegan County Rem	on. iron and Remon. c	ap in monument box.		37.11	OF MA	CHILL	٠.		
elephone pole Remon. tag S	Z side 16° V 00 20:	•	3	\$ E(1).		. 4.	14		
corner brick foundation)	house 338° 236 11'		ž.	*	STEVE	1			
corner brick building 32	5° 111.34'		Ĕ	I	AMPE	N 🤾	~ <u>~</u>		
elephone pole Remon. tag E	side 203° 219 Ant		₫	٠	LAND	;	=		
enter Hichigan Bell box 14	1* 46.651		트.	"ე: St	ͿϏΫϾϒͼ	UR 🚶	~ [₹]		
			1	~~.	NU.	,	જે <i>કે</i>		
			7	<i>σ</i>	3/4/9		150		
			,	14. 85	· · · · · ·	clili,	Hr.		
				Mille	LANG	THILL.			
م س ا ده		es established to perpetuate loca		11	atttiri,	1111.			
gned by Steven I	amunan	Date December	12, 199	6					
	- 1		-,	-					

UEER 0005 PAGE 497