<

# SECTION

#### ALLEGAN COUNTY REMONUMENTATION

### LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Ear.	~~	ners	
TO:	COL	Heis	

Allegan

Located In:

Corner Code #

1. Public Land Survey

T4N R14W

2. Property Controlling in Section

3. Miscellaneous Property in Sec.

M - 10Overisel Twp.

Register of Deeds Stamp & File Number


 $\circ$ 

Š

, Recorded Plat 5. Private Claims

I, Kirk L Van Order in a field survey on Nov 1, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

# M - 10

(1)

North E. side Sec. 25

40.00 Set 1/4 sec. post

Beech 10"

N.88°W.

20 links 31 links

N.07°W.

APPROVED REMONUMENTATION CORNER

P.A. 345 OF 1990

ALLEGAN COUNTY

NOU DATE APPROVED

COUNTY REP.\_

(continued on back of sheet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

 $\overline{\text{Fd.}}$  1-1/2" x 36" iron pipe and the following witnesses:

Nail in S. side 11" elm (now dead)

W.SW

88.93'

Nail in N. side 6" (now 7") ash

SW

92.43'

Power pole has been replaced Removed fd. iron pipe and replaced with standard Allegan Co. monument and is accepted as a careful and faithful perpetuation of the position of the original corner.

Peer group approved Nov. 9, 1999.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

## M - 10

Standard Allegan Co. Remon. monument (3/4" x 36" steel rod w/red cap #23520)

Nail & Remon. tag in E side power pole Nail & Remon. tag in N side 7" ash Nail & Remon. tag in N side 14" maple

23520

AZ 355° AZ 235°

78.89 92.45'

Nail & Remon. tag in SW side 10" ash

AZ 90° AZ 140° 82.17' 70.27'

Signed by Surveyor's Michigan License No Date 12-30-1999,

MAR 07 2000

SECTION

```
Section A (continued from Page 1)
M-10
Overisel Twp., T.4N., R.14W
```

```
Overisel Twp., T.4N., R.14W
     LCRC recorded in Liber 1 on Page 391 by Donald A. Ratekin, dated June
(2)
     6, 1972
     Witness card Fd. stone - set 1-1/2" iron pipe
                   10" ash
                                 SSW
                                          72.4'
                    4" sycamore
                                          59.75
                                 SW
                   St sign
                                 N
                                          37.0'
                   P pole
                                 NNW
                                          82.0'
                   1-1/2" iron pipe w/stake inside
                                 s45°W
                   12" ash
                                           72.4'
                                 s60°W
                   6" sycamore
                                           59.75
                                 N10°W
                                           31.75' (was moved)
                   St. sign
                                 N05°W
                                           82.0'
                   P. pole
     Holland Engineering, Inc. info. Same info as in No. 2 above
(3)
(4)
     Kirk L. Van Order, R.L.S. survey recorded in Liber 1191 on Page 550,
     dated April 10, 1986
       Fd. 1-1/2" pipe 16" ash
                       SW
                              72.4'
       9" sycamore
                       SW
                              59.75'
       St. sign
                       NW
                              31.75
       Power pole
                       NW
                              82.0'
(5)
     Kirk L. Van Order survey, dated May 17, 1989
       Fd. 1-1/2" pipe
       Same ties as in No. 4 above
(6)
     Kirk L. Van Order survey dated, April 17, 1990
       Fd. 1-1/2" pipe
       Same ties as in No. 4 above
     Kirk L. Van Order survey, dated May 12, 1993
(7)
```

Fd. 1-1/2" pipe
Nail in S. side 11" elm W.,SW 88.93'
Nail in N. side 6" ash SW 92.43'
Nail in NW side 12" elm S.,SW 100.96'

PK in E. side power pole N., NW 82.49'