

ALLEGAN COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
 Filing Requirement of Act 74, Mich. P.A. 1970

1993 DEC 30 PM 2:41
 REGISTER OF DEEDS
 ALLEGAN COUNTY, MICH.
 FILED

For corners in
COMMISSION
 Allegan (County)

1. Public Land Survey	T <u>4N</u> R <u>15W</u>	<u>A-1 (NW Sec 6)</u>
	T _____ R _____	<u>Fillmore Twp.</u>
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

A	B	C	D	E	F	G	H	I	J	K	L	M
2	5	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, David R. Greer, in a field survey on November 22, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules thereto as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Government Notes 1831 Post

- A. Description of original monument and accessories and/or subsequent restoration:
- | | |
|---|--|
| A-1
Recorded in Liber 3, Page 61, March 22, 1976
Iron found in monument box
Nail in side of Power Pole SE 39.91'
CL Hydrant NE 44.49'
Nail in Side of Guy Pole NW 37.99' | A-1
Recorded in Liber 2, Page 377, March 27, 1975
Found iron in monument box
Nail & Cap in Guy Pole NW 380.00'
PK Nail in NE Side Power Pole SE 39.90'
SW Cor 12" x 12" Concrete NE 45.70'
Cor of Fence Post |
|---|--|

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- A-1
Found iron in monument box and accepted it as a careful and faithful perpetuation of the position of the original corner.
Nail in Side of Power Pole SE 39.91'
CL Hydrant NE 44.99'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- A-1
Replaced iron in monument box with A. C. Remonumentation Iron & Cap
 AZ - Michigan State Grid Direction
- | | |
|--|---------------------|
| A.C. Remon tag & nail in NW Side 18" Pine | AZ. 48°56' 137.78' |
| A.C. Remon tag & nail in N Side 12' Pine | AZ. 112°18' 103.00' |
| A.C. Remon tag & nail in S Side 16' Maple | AZ. 244°51' 98.83' |
| A.C. Remon tag & nail in NE Side 14" Maple | AZ. 310°17' 75.70' |
| A.C. Remon tag & nail in S Side 14" Pine | AZ. 70°12' 148.39' |
| A.C. Remon tag & nail in E Side 12" Oak | AZ. 136°12' 104.10' |



Signed by David R. Greer Date 12/14/93
 Surveyor's Michigan License No. 16042