APR 0 7 1998 Allegan County Remonumentation LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 For corners SECTION Allegan Located In: Corner Code # 1. Public Land Survey T 4<u>N R 15W</u> D-13 South 1/4 corner, Section 32 Fillmore Twp. 2. Property Controlling in Section Register of Deeds Stamp & File Number 3. Miscellaneous Property in Sec. 4. Lot No. __, Recorded Plat BCDEFGHIJKLM 5. Private Claims 26... - 5 4 -3--2----1 -3 I, Steven Lampen , in a field survey on December 29, 19 97.

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: 4 -7-.. A -10 -ii - 12 5 --18 -17 -16 ..·15 -14 -13 7 8 -19 20 -21 -22 23 -24 9 10 -30-NOTE: Not more than 4 corners, all in the same town and range, may be recorded 29 --28 27 -26--25 on this certificate. 11 -31--32 -33 34-35 36 Description of original monument and accessories and/or subsequent restoration: A. D-13 D-13 to C-13, Hicks 1876 = 2637.36 meas. 1997 2637.93 G.L.o. Beech 7" N 63 1/2 W 33 Do. 16 N 74 E 62 D-13 to E-13, Hicks 1876 = 2637.36 meas. 1997 2636.73 J. W. Hicks, 5/11/1876 Stake and stone South 1/4 post - fd stone placed 1" iron on top (10/13/67) 4" white post N 23.44' 8" Maple NW 57.6' 22 cor. house NW 106.0' Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found iron in monument box 8" Maple NW 57.6' SE cor. house NW 106.0' Replaced iron with 3/4"x24" Allegan County Remonumentation iron and Remonumentation cap and accepted it as a careful and faithful perpetuation of the position of the original corner. This corner was approved by the Allegan County Surveyors Peer Group on December 30, 1997. APPROVED REMONUMENTATION CORNER P.A. 345 OF 1990
ALLEGAN COUNTY
DATE APPROVED 12-3c-9
COUNTY REP. K. V. C. COUNTY REP. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Allegan County Remonumentation iron and cap in monument box Azimuth = Michigan State Plane grid direction direction OF Michigan Remonumentation tag S. face power pole 75° 21' 132.34 337° 57' 102.46 317° 17' 105.81 STEVEN STEVEN SE corner garage foundation SE corner house brick 270° 25' 162.30 D-1, T3N, R15W monumentation tag N side power pole 290" 41 ' 103.98 Nail in E side 20" Maple Nail in SW side 24" Maple 332* 28' 58.06 309° 591 Centerline East and West asphalt road 180° Signed by Steven Date DECEMBER 31

USEP 0006 PAGE 081

Surveyor's Michigan License No. 37279

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYDRS, JAN. 28, 1971
MEVISED MAY 14, 1975
KVICED JAN., 1980
ADAPIED FOR WORD PROCESSING MARCH, 1893