SURVEY & REMONUMENTATION

ALLEGAN COUNTY REMONUMENTATION	
APR 0 7 1998 LAND CORNER RECORDATION CERTIFIC	ATE
Filing Requirement of Act 74, Mich. P.A. 19	
For corners in	Éz (Î
Allegan SECTIO Nocated In: Corner Code #	JAN T
(County)	ASI C
(**************************************	21 Z
1. Public Land Survey TAN R 15W K-6	
TR <u>W 1/4 Cor</u> .	ED ED
<u>T R Sec. 13</u>	
T_RE_1/4_Cor.	22 the
2. Property Controlling S T R Sec. 14 in Section S T R Fillmore Typ	2
7.1	
9. Miscellaneous S I R Property in Sec. S T R	· ·
1 topolity in ode.	Register of Deeds Stamp & File Number
•	
4. Lot No. Recorded Plat	
4. Lot No, Recorded Plat	A B C D E F G H I J K L
	2 - 6 - 5 - 4 - 3 - 2 - 1 -
	3 1 1 1 1 1 1 1 1
1 Virk I Van Order is a feld superior Tune 0 40.07 de bescheete Materials	
I. Kirk L. Van Order, in a field survey on June 9, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the comer points mentioned in lines 1 and 2 above were in	4 / 8 9 10 11 12
conformance with regulations and rules therefore as required in the current manual of survey instructions of the	5
United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or	6 -18-17-16-15-14-13-
that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan	7
Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below.	8 19 20 21 22 23 24
:	
NOTE: Not more than 2 corners, all in the same town and range, may be recorded	9
on this certificate,	10 -30 -29 -28 -27 -26 -25
·	11
	12 31 32 33 34 35 36
A Deposition of arisinal manufactured and appearation and less whose work and appearations	13
Description of original monument and accessories and/or subsequent restoration:	
<u>K-6</u>	
(1) GLO Mar. 21, 1832, Calvin Britain, D.S.	
North between Sec.s 13 & 14	
40.00 ch. Set quarter Sec. post	
Hemlock 14" South 27 links	
Elm 18" N26°E 15 links	
(2) County Surveyor notes, Oct. 24, 1879	•
Show stake at corner (no ties) (conti	nued on back of sheet)
	•
B. Description of corner evidence found and/or method applied in restoring or reestablishing con	ner:
<u>K-6</u>	
Kirk L. Van Order, P.C. Remon. survey dated June 9	, 1997
Fd. 1/2" capped re-rod by using tie info. in Part	A, Item No. 14. And is
accepted as a careful and faithful perpetuation	of the position of the
original corner.	
- 10 100B AP	PROVED REMONUMENTATION CORNER
Peer group approved June 10, 1997.	P.A. 345 OF 1990
	ALLEGAN COUNTY
	TE APPROVED 6-10-97 DUNTY REP. K.V. 0.
į a	DUNTY REP. K.V. 6.
C. Description of monument for corner and accessories established to perpetuate locating the po	esition of the corner.
*Note: Remon. iron to be set after road construct	tion near the
K-5 A.C. Remon. iron AZ 00°00′00	
SE corner of red brick house AZ 37°40′03	
SW corner of red brick house AZ 26°34'15	
Nail & Remon. tag in N. side p. pole AZ 94°10'43 C/L RR spike in Russcher Road AZ 359°57'3	
C/L RR spike in Russcher Road AZ 359°57'3 Fd. 3/4" steel rod in mon. box in	
Russcher Road AZ 00°16′24	" 109.65'
Nail & Remon. tag in S. side p. pole AZ 265°09'4	3" 136.35'
K-7 fd. 3/4" iron pipe AZ 180°13'0	
Signed by find of than the Date	12-31-97
Surveyor's Michigan License No. 23520	•
D 1 -5 0	

UED 0006PAGE 093

<u>Section A</u> (continued from Page 1) <u>K-6</u> <u>Pillmore Twp., T.4N., R.15W.</u>

1" iron in mon. box

C/L Russcher Rd.

D.A. Ratekin survey, July 6, 1971, L. 794, P. 92 Iron \$45°W St. sign 22.8' N60°W N. end CMP 21.9' D.A. Ratekin LCRC, July 29, 1971, L. 1, P. 93
1" Iron (same ties) D.A. Ratekin survey, Dec. 30, 1975, L. 899, P. 389 1" Iron (same ties) D.A. Ratekin survey, Aug. 18, 1977 1" Iron (same ties) H.E.I. tie sheet, print out - received Jan. 31, 1997 1" iron (same ties) K. Van Order survey, Dec. 29, 1982, L. 1027, P. 716 Fd. bent iron - removed and set capped iron Power pole W,SW 135.95 C/L Tele. cable box NW 99.35' 8" Apple 10" Pear NE 143.43' N,NE 175.22' (9) K. Van Order survey, Sept. 2, 1986, L. 1186, P. 174
Capped iron (same ties)
(10) K. Van Order survey, Aug. 25, 1987, L. 1243, P. 06 Fd. Capped Iron (same ties)
(11) Wightman-Moored tie info. Sept. 1, 1989 Fd. capped iron Nail E. side power pole W,SW 135.95 C/L Tele. box 99.35' Nail E. Side Apple NE 143.43 PK & Russcher Rd. 3/4" Iron in Mon. Box C/L Russcher N55°E+/-98.10' 109.6' S 1/8 Post, NE 1/4 1349.5 (12) K. Van order survey, Nov. 28, 1989 Fd. capped iron Power pole W,SW 135.95' C/L Top tele. ped. 11" Apple 12" Pear NW 99.35' ΝE 143.43 N,NE (13) K. Van Order survey, May 17, 1991 Fd. capped iron (same ties) (14) Kirk L. Van Order survey for A.C.R.C. dated Nov. 25, 1996 Fd. 1/2" capped re-rod Fd. PK nail in N. side power pole E 76.43' Set nail in S. side power pole W,SW 136.45' C/L Top tele. ped. N,NW 99.35'

Ν

110.674

 $P_{i} \in \mathcal{P}_{i}$