APR 2 5 1995

CG	LAB	211	21	<i>(</i> ግ)\	į
\$ 3 W G		846C II			J

5. Private Claims .

ALLEGAN COUNTY REMONUMENTATION				
LAND CORNER RECORDATION CERTIFICATE				
Filing Requirement of Act 74, Mich. P.A. 1970				

REGISTER OF DELTAS ALLEGAN COUNTY, MICH	94 DEC 30 PH 12: 16	FILED
E.	ਨ	

-Allegan Located in: Corner Code ## 1. Public Land Survey 4N\_ F 16W J-3-N1/4 Cor-\_ R Sec-11-R Laketown Twp. 2. Property Controlling R in Section R Miscellaneous Register of Deeds Stamp & File Number Property in Sec. \_ , Recorded Plat

I. John P. Clapp , in a field survey on <u>December 12</u>, 19 94 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below.

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

J-3 Gen. Land Office Survey Notes1831 Lucius Lyon, Surveyor Set Post 9" Hemlock N89°E 7 links 6" Beech S89°W13 links

J-3 Recorded in Liber 1, Page 310, May 4, 1972 3/4" re-rod in mon box NW Cor Hse S10°E 96.15' 18" Ash S05°E 69.80' 8" Spruce \$40°E 53.2" Power Pole N05°W 44.6'

J-3 Recorded in Liber 1 Page 313, May 4, 1972 1" Iron NW Cor House S15°E 96.09' Power Pole N5°W 44.5

See reverse side for additional

B. Description of corner evidence round and or method applied in restoring or reestablishing corner:

APPROVED REMONUMENTATION CORNER
P.A. 345 OF 1990
ALLEGAN COUNTY DATE APPROVED 12-13-94
COUNTY REP. Said 1. 10-15

J-3

Found 3/4" steel bar in monument box and accepted it as a careful and faithful perpetuation of the position of the original corner.

Found P.K. Nail in S Side Power Pole Found P.K. Nail in W Side Power Pole

AZ. 256° 98.55' AZ. 354° 44,86

NW Cor. Brick House AZ. 170° 96.10

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set A.C. Remon Iron and Cap in Monument Box

A.C. Remon Tag & Nail in S Side Power Pole 98° 236.46 A.C. Remon Tag & Nail in S Side 16" Pine 246° 132.43 A.C. Remon Tag & Nail in W Side Power Pole AZ. 354° 44.95 NE Comer Brick House 155° 114.44

John P. Clapp Surveyor's Michigan License No.

CLAPP SURVEYOR

W:\Docs\Surv\Re

DETR 0005 PAGE 122

Page 1 of 2

J-3 - March 1, 1880 Old County Surveyor Records show "stone" with cross. No Witnesses

J-3
Recorded in Liber 2, Page 41
Nov. 21, 1972
3/4" Iron in Monument Box
Power Pole WSW 98.65'
Power Pole N 44.83'

OPEN TROPERSON A TROPERSON A TROPERSON A TROPERSON A TRANSPORTATION OF TRANSPORTATION AND TRAN

J-3
Recorded in Liber 3, Page 69
April 16, 1976
Found Iron
Power Pole N5°W 44.6'
8" Spruce S40°E 53.2'
NW Cor House S10°E 96.15'
18" Ash S5°E 69.8'

**Billian**kata kemeranan kelonger