APR 2 5 1995

## ALLEGAN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

(Fall	Æ٩	S.	20	11 3	h. F
1 .(Fail)	بأداخ	44.	Con C	14.7	٠,

E	NOICESIMAN	, Filing Require	ement of Act 74, Mich. P.	A. 1970 مرايون مرايون مرايون	3 46		
_	-Allegan <sub>Countyr</sub>	Located in:	Corner Code ##		DEC 30	T	
1,	Public Land Survey	T <u>4N</u> R 46W T <u>n</u> R <u>—</u> T <u> R</u>	—J-10 Center— —Sec 20——— —Laketown Twp.	C. C. both CR OF DIF 28 ICOLIN FY. MICH	0 PM 12: I	EO	
2.	Property Controlling in Section	S T R S T R		<u> </u>	7		
3.	Miscellaneous Property in Sec.	S T R		Register of Deeds Starr	ıp & File	Number	
		Recorded Plat	· · · · · · · · · · · · · · · · · · ·	ABCDEI	<b>7 6 н</b>	IJĸı	L
							T

above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

J-10 This position not established by original Government Surveyors. Recorded in Liber 3, Page 306, April 16, 1981

2" Pipe in CL of old grade at the intersection of the 1/4 lines

Power Pole SE 31.40 Consumers Power Co. pipe above ground NE 31.90 Consumers Power Co. pipe above ground NW 34.40

5.5' S of line between Cons. Power Co. Pipes

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

APPROVED REMONUMENTATION CORNER
P.A. 345 OF 1990
ALLEGAN COUNTY
DATE APPROVED
13 -13 -14 COUNTY REP.

J-10

Found 2" iron pipe in centerline of old grade at the intersection of 1/4 lines

SE

31.40

Consumers Power pipe above ground NW 34,40

This position not established by original Government Surveyors. This monument is accepted as the best available evidence of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

Found 2" Pipe. Set Allegan County Remonumentation Iron & Cap at intersection of 1/4 lines

A.C Remon Tag & Nail in SW Side Power Pole AZ. 153° 32.13 A.C. Remon Tag & Nail in SE Side 6" Oak AZ. 289° 25.88 A.C. Remon Tag & Nail in SE Side 8" Maple AZ. 221° 41.40 A.C. Remon Tag & Nail in N Side 8" Oak 103° Α7 59,03' A.C. Remon Tag & Nail in SW Side 4" Oak AZ. · 318° 36.26

Signed by John P. Clapp

Surveyor's Michigan License No. 409

Traverse off 1320 1040 road

Page I of 2

151-0005 PAGE 126

OF MIC

UST 0005 PAGE 127

J-10 State Plane Grid Azimuth

K-10	ΑZ	91-14-42	2635.068
J→lI	ΑZ	179-19-53	2618.336
I-10	ΑZ	271-14-42	2641.751
J-9	ΑZ	359-19-53	2649.6891

APPROVED RESPONDED TO THE MEDICAL SECTION OF THE PROPERTY OVER COUNTY HERE THE PROPERTY HERE THE PROPE

**等等数数数数**字型之外,14.45。22.152.32.3