LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Alpena	Located In:	Corner Code ##					•	ı.			
1. Public Land Survey	T 29N R 6E T 29N R 6E T R	D-6 E-6									
 Property Controlling in Section Miscellaneous Property in Sec. 	S 17 T 29N R 6E S 17 T 29N R 6E S T R S T R	13 9	Reş	gister of I	Deeds	Stam 	p & F	ile N	umt	er	
4. Lot No	Recorded Plat			A B	C D	E F	G	H	J 2-	K L	 - -
do hereby certify that under ro in lines 1 and 2 above were current manual of survey ins	in a field survey on aguirements of P.A. 74, Michigan P.A. in conformance with regulations and tructions of the United States Depart of a Court of Law and/or that the corne	d rules therefore as required tment of the Interior, Bureau of tripoints mentioned in lines 3, 4	in the Land and 5	5 6 18 7 8 19	17-	9 16		15	-11- -14- -13- -23-		13-

expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as

A. Description of original monument and accessories and/or subsequent restoration:

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: D-6 - Set at computed true intersection of 1/2 lines
- 13 Set by standard survey procedure for subdivision of a section. 9 - Set by standard survey procedure for subdivision of a section.
- E-6 Set midway and on line between found section corners.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-6 - Center of Section 9 - El/8,E-W ½ Line 13 - Center SW 5/8" bar w/cap 6" Cedar N25 W 8.2' 12" Cedar S41 E 27.5' 5/8" bar w/cap 8" Spruce S33 E 25.3' 14" Balsam S58 W 27.6' D.N.R. Monument 14" Ash N32 E 17.0' 10" Ash S51 W 37.5' 5" Spruce S72°W 8.7'

E-6 - East 1 corner D.N.R. Monument 6" Cedar N17 W 13.8' 10" Cedar S37 E 13.9' 4" Cedar S56 W 9.3'

JOHNBON LAND WILLIAM STATE

OF MICH

Date

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND BURYEYORS, JAN. 20, 1971 REVISEO MAY 14, 1975 REVISEO JAN., 1983

Signed by . Surveyor's Michigan License No.