REMONUMENTATION LIBER 1 PAGE 318

19949 A Speng County Remonumentation corner

APR LAND CORNER RECORDS

Filing 7 RECORDED ALPENA COUNTY MI. DEC 8 10 11 AM '94 LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 orping a Johnston For corners in Alpena County) REGISTER OF DEEDS Located In: Corner Code :## G-10 (Wk, 27) T 29N R 7E Public Land Survey T \_\_\_\_\_ R \_ Ossineke Two. \_\_ R \_\_\_\_ \_\_\_ R \_\_\_ Property Controlling in Section \_\_ T<sub>\*</sub>\_\_\_ R \_ Miscellaneous \_\_\_T \_\_\_\_R \_\_\_\_ Register of Deeds Stamp & File Number Property in Sec. \_\_\_\_, Recorded Plat \_ Private Claims Thomas L. Fabis , in a field survey on \_ <u>May 25</u> do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A Description of original monument and accessories and/or subsequent restoration: G.L.O. Survey by Lewis Clason - Set  $\frac{1}{2}$  post and referenced: Spruce 11 - N56°W - 25) 1839: (Tam 10 - S65°E - 25, Special County Survey by Wm. H. LeRoy - Set 3" sq. cedar stake & referenced. County Survey by Jos. W. McNeil - & stake incroad bed. County Road Plan - 2" iron and referenced. 1892: 1910: 1976: 1976: Survey by David B. Guthrie - Exis. nail and referenced. 1982: Survey by Duane MacNeill - Found Mon. Box. 1984 & 1992: Surveys by Earl T. Lewis - Found Mon. Box and referenced. 1988: Survey by David B. Guthrie - Found iron stake in Mon. Box. B Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 1" iron rod in Monument Box and three existing witnesses as per 1992 Survey by Earl T. Lewis and one witness (S85°E - 95.88' - N.W. Cor. Hse.) as per 1976 County Road Plan and 1976 Survey by David B. Guthrie. This corner position is compatible with 1994: county and local surveys and is accepted as a careful and faithful perpetuation of the position of the original corner. Description of manument for corner and accessories established to perpetuate locating the position of the corner: Set 3" dia. aluminum cap, stamped to identify corner over existing 2"iiron rod in 1994: Monument box. Existing witnesses are: Fe. Post - N85°E - 53.65' P. Pole - S20°E - 116.63' Pipe - West - 50.00' N.W. Bldg. Cor. - S85°E - 95.90' PEER APPROVED Oct 27 1994 FARIS LAND

ERNOED

LAND

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN.. 1983