1994 Alpena County Remonumentation Corner

LAND CORNER R

For corners Filing Requirementation Filing Requirementation Corners Report Corners Report Filing Requirementation Corners Report Corners Report Filing Requirement

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

USES

DEC 12 9 31 AH 194 Mariene a. Johnston

REGISTER OF DEEDS

Located In: Corner Code ## 1. Public Land Survey T\_ 2. Property Controlling R in Section 3. Miscellaneous R Property in Sec.

Register of Deeds Stamp & File Number

4.	Lot No, Recorded Plat		
5.	Private Claims		
		• .	

, in a field survey on \_\_\_ Earl T. Lewis 94 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(GLO) July 23, 1839, Lewis Glason set post, witnesses given: Y. Pine 8, S 46 W, 36 / Aspen 12, N 34 W, 11.

1894, Fred A. Rice, no monumentation or witnesses given.

1973, Edward LaCross, found iron witnesses given: Power Pole, N 45° W 46.49 teet / Clump Basswood S 45° W 55.0 feet.
1976, David B. Guthrie, found 1/2" rod, witnesses given: S 45° W 56.50' Power Pole / N 05° W 48.25' Power Pole / S 45° E 60.85' Fence Corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 5/8" rebar raised with 1/2" rebar.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1994, Place Appropriately stamped Alpena County Remonumentation Aluminum Cap on existing 1/2" X 24" rebar in monument box, witnessed: North 48.10' Power Pole

S 450 W 56.50' Power Pole (found PK nail) N 100 E 23.00' Rd. Sign S 200 E 53.10' Stop Sign

N 05° E 48.10' Cut off Pole (found nail) S 15° E 87.50' 4" Cedar S 75° W 80.40' 4" Willow

P.A. 345 ALPENA COUNT

		_		N = = = = h = + +	-	1004
	-		_	December	ο,	<b>TAA4</b>
 ~ ~ //		Leni _	Date		•	