REMONUMENTATION

REMONUMENTATION		,	CARAB BIRS
OCT 2 7 1999	LAND CORNE	ounty Remonumentation R RECORDATION CERT	FICATE
For corners in SECTION	Filing Require	ement of Act 74, Mich. P.	a. 1970 I State of Michigan
			County of Alrena
Alpena Loc (County)	ated in:	Corner Code #	Recorded
(County)		•	01-04-1999 09:13:03
, 1	T_29N_R7E T_29N_R8E TR	M-10 A-10	Kathy J. Matash REGISTER OF DEEDS
, ,	r R		
	R		,
Property in Sec. ST	R		Register of Deeds Stamp & File Number
	:		
4. Lot No. Recorded Pla	t		
4. Lot No, Recorded Pla 5. Private Claims			
			3 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
			1 7 8 9 10 11 12
I, Daniel T. Kibbe , in a field survey or			
requirements of P.A. 74, Michigan P.A. of 1 were in conformance with regulations and ru	970, the corner point iles therefore as requi	s mentioned in lines 1 and 2 at red in the current manual of su	rvey 6 18 17 16 15 14 13
instructions of the United States Department decree of a Court of Law and for that the or	nt of the Interior, Bur	reau of Land Management or i	by a 7
conformance with the rules of the Michigan	n Board of Land Surve	eyors or by a Decree of a Cou	
Law; established, re-established, monumente	id, recovered, found a	is expressed below:	10 30 29 28 27 26 25
NOTE: Not more than 2 corners, all in the	same town and rang	e, may be recorded	11
on this certificate.			12 31 32 33 34 35 36
			13
Set large cedar stake and made NW 1973: Survey by James L. Scott- Found 1/3 Twin 6" oak-N45E-65,58' 1983: Survey by Duane R. MacNeill-Found Recorded Liber 2, Pg 245. 1985: Survey by Earl T. Lewis-Existing 1/2'	ound 1/4 corner on Wo T. Referenced: W.Pine 2" iron rod 2' below s 1/2" rerod. Referenced " rod, Referenced: Fi	est line of 30. Found one OBT is 12-N63W-56, W.Pine Stump surface and raised with 1/2" road: 12" red oak-S60W-51.35', sence post-East-25.9', P.Pole-N	plain W.Pine 12-N63W-56 partially burned, other gone. 30-N37E-46 1/2. J. Referenced: P.Pole-N45W-51.45', P.Pole-N40W-51.35', Fence post-Due East-25.80'.
B. Description of corner evidence	found and/or me	ethod applied in restoring	or reestablishing corner:
1998: Remon Survey by Daniel T. Kibbe-Fo 19237.	und 1/2" rebar 1'± E	ast of N-S CL Lytle Road on ol	d fence lines East & West. 33' West is a ROW iron
This corner postion is compatible to perpetuation of the position of the		urveys. This corner position is	accepted as a careful and faithful
C. Description of monument for	or corner and acc	essories established to p	erpetuate locating the position of the corner:
1998: Placed 3" Alpena County cap stan Referenced: Found tag in corner fence post	•	orner over 1/2" iron rod.	
Found tag, set tag in P.Pole-N3 Found tack, set tag in P.Pole-N Found PK, set tag in 14° Oak-	32W-51,50' I31W-51.51'	V	P.A. 345 ALPENA COUNTY PEER APPROVED 12/11/98 OLD B. Co
Set tag in Maple cluster-S20E-			D. DB lin
		SE OF MICH	Oct 11.
(STILL	
	**	DANIEL T. KIBBE LAND SURVEYOR No.	
A -	1 - SE	37278 JAND SURVEY	
Signed by	Wiff.	Mount	Date <u>December 17, 1998</u>
Surveyor's Michigan License No	37278		