MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_29 NR_9 E ...

			-		_¥ībēuæ		_ COUNTY
DESCRIPTION	OF	CORNER	Corner common	of T2	ections 32 9N, R9E	2 & <i>3</i> 3_0	n_ s outh
DESCRIPTION	OF	CORNER	MONUMENT_4#	p <u>ipe</u> 1	with 4" br	see cer) <u> </u>
WITTNESSES	то	CORNER					
			8# Cedar		N72W_	-	27½ links
			7" Cedar	_	N20E	-	30½ links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a survey in this area. Found a very old square post, scribed 32 on NW face in place. Corner faced by a Cedar NBT which was marked over 30 years ago as determined by ring count. One possible original B T is down and rotted. Checks government record for stream crossing east.

Closing corner for Sections 4 & 5, T28N R9E is 29 links east.

Corner was placed and witnessed April 12, 1957.

SURVEYORS SEAL

SIGNED_ Silly & Suckles __ DATES/9/57_