Lot No. _____, Recorded Plat

2 PAGE 32 LIBER

OU3327 RECORDED ALPENA COUNTY MI.

LAND	CORNER	RECO	RDATIO	N CEF	RTIFI	CATE
Cilina	Danisan	ant of	Ant 74	Mich	DΛ	1070

Alpena (County)		 .	Located In:	Corner C	Corner Code ##		
1.	Public Land Survey		T 30N R 071 T 30N R 061 T R T				
2.	Property Controlling in Section	s s	T R T R				
3.	Miscellaneous Property in Sec.	S S	T R T R				

Jun 17 10 58 AM '96 Harry A. Matash REGISTER OF DEEDS

Register of Deeds Stamp & File Number

5. Private Claims			2 - 1			3_	
Earl T. Lewis	in a field survey on April 10	. 19 ⁹⁶	4	8-	- - -	10-	
do hereby certify that under req in lines 1 and 2 above were in	uirements of P.A. 74, Michigan P.A. of 1970, the conformance with regulations and rules there	efore as required in the	618	-17-	16-	15	L
Management or by a decree of a above were in conformance with	ictions of the United States Department of the Court of Law and/or that the corner points men In the rules of the Michigan Board of Land Surve	tioned in lines 3, 4 and 5 eyors or by a Decree of a	819_	20	21-	22	
Court of Law; established, r expressed below:	e-established, monumented, re-monumented	, recovered, found as	1030	29	28	27_	F
NOTE: Not more than 4 co	orners, all in the same town and range, m	nay be recorded	11		+	+	t

on this certificate.

Description of original monument and accessories and/or subsequent restoration:

Set corner. Witnesses given: Cedar 22 S 41° W 31, Cedar 16 N 40° W 14 1839: Lewis Glason

1885: W. Mirre

Set 4"x3" cedar stake w/cans, a piece of iron, some crockery & a piece of a lamp.
Found 1/2" iron. Wit. given: N45 E 44.97' Power Pole, S45 W 45.45' Fe. Post, N50 W 58.65' Fe. Post 1977: D.B. Guthrie

Found 1/2" rod. Wit. given: S50'W 58.25' Power Pole, N50'W 58.65' Fence Post 1980 & 85: E.T. Lewis

Used corner. No monumentation or witnesses given. 1985: Ed LaCross

Used corner. Found 1/2" rod. Wit. given: S 45° W 52.25' Power Pole, N 45° W 58.90' Fence Post 1990: E.T. Lewis, P.S.

1992: D.B. Guthrie Fd 1/2" rod. Wit given: N66°E 59.98' Cble Mrkr, N55°W 59.00' Fe. P., S83°W 48.70' Stop Sign, S75°W 58.44' U.P.

Recorded corner in Liber 2 of Corners, pg. 13. Found 1/2" rebar. Witnesses given: N45°E 59.44' Corner Tele. Pedestal, N50°W 59.20' Tag on Fence Post, S50°W 58.53' Tag on Power Pole 1995: G. St. Charles

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1996: Found 1/2* rerod in centerline of road.

SURVEY & REMONUMENTATION

JUL 2 3 1996

COMMISSION

P.A. 345 ALPENA COUNTY
PEER APPROVED 5/5/46

AD A. Coo

Description of monument for corner and accessories established to perpetuate locating the position of the corner: Placed appropriately stamped Alpena County Remonumentation 3" aluminum cap on existing 1/2" rerod in monument 1996: box.

Witnesses given:

\$ 55' W 58.50' Power Pole N 60' W 63.65' Pence Post S 45° E 89.10' 6" Cedar S 60' E 78.90' 6" Cedar

OF MICH EARL T LEWIS ROFESSION 27452 POFESSION

Date J	June 12, 1996
Signed by	
Surveyor's Michigan License No. 27452	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975