Alpena County	Remonumentation
---------------	-----------------

LIBER

2 PAGE 21

OO3316 RECORDED ALPENA COUNTY MI.

		LAND COM	EN NECONDATION CENT	IFICATE		•						
	or corners in	Filing Requi	rement of Act 74, Mich. P	.A. 1970	Ju	v 17	10	58 A	1 '9	6		
λl	pena ·	Located in:	Corner Code ##		. 1					-		
	(County)				44	athy	169	Indo	۸٤.			
1.	Public Land Survey	T 30N R 07E			RE(i 17 Outy Disti	ER O	F DE	EDS	3		
	٠.	T R T R	 									
2.	Property Controlling	S T R S T R										
3.	Miscellaneous	S T R		Register	of De	ade S	tamn	2 Eila	Man	mhe	_	
٠.	Property in Sec.	s r R		negister		- Cus S	tamp	a riie			•	_
4.	Lot No.	, Recorded Plat			R (E	е н	1 J	ı K	1. 1	L
5.	Private Claims				† 1		` 	ĬΪ	<u> </u>	Γ̈́	Ť	_
	•		•	2	- 6	— ʻ \$—	- ∤-	 	+-4	! —	-1-	-
				3 -	╌┼╌┼					-		-
	Pami M. Louis	Nav 11	96	4	- }+		— þ —	 0-	- 1	<u>'</u> 1	12-	-
١, .	Dail 1. Dewis	, in a field survey on	, 19	5						┥		_
do	hereby certify that under	requirements of P.A. 74, Michigan P.F. in conformance with regulations a	A, of 1970, the corner points ment and rules therefore as required i	ioned 6	-18	-17-	16	15		4-	<u> — </u> 3_	_
in Cu	errent manual of survey in:	structions of the United States Department	artment of the Interior, Bureau of	Land 7	+	——		 	4-	\sqcup		_
Ma	anagement or by a decree	of a Court of Law and/or that the core	ner points mentioned in lines 3, 4	and 5 a	-19	_20	21	-22-	 	3_	<u></u>	_
ab	ove were in conformance	with the rules of the Michigan Board	of Land Surveyors or by a Decre	e ola 9	44	\perp		1		\sqcup		_
	ourt of Law; established pressed below:	I, re-established, monumented, re	-monumented, recovered, tour	10 45	_30		 28	27-		<u> </u>		_
	•	corners, all in the same town a	and range may be recorded	11		1				Ш		_
N	OTE: Not more than 4 on this certifica		and lange, may be recorded	12		_12_					36_	_
	, on this vertified		•	13	أ_أ_ا	<u> </u>	Ĩ					_
Α.	Description of origin	al monument and accessories a);	-							

Description of corner evidence found and/or method applied in restoring or reestablishing corner:
6: Set 1/2" x 18" rerod in monument box in centerline of Herron Road and in line with old fence to the 1996: South. Found nail in asphalt 1" South of road centerline and 4.5' East of set rerod.

Set corner in road bed. No witnesses given.

SURVEY & REMONUMENTATION

1910: J. McNeil

JUL 2 3 1996

COMMISSION

P.A. 345 ALPENA C PEER APPROVED 5/16

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Placed appropriately stamped Alpena County Remonumentation 3" aluminum cap on set 1/2" x 18" rerod 1996: in monument box.

> Witnesses given: S 10° E 33.40' Power Pole South 127.70' 6" Apple N 45° E 99.95' Fence Corner N 50° W 63.10' Telephone Riser



	, shifting.
-6	June 12, 1996
Signed by East Ti	Date
Surveyor's Michigan License No. 27452	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 19 REVISED MAY 14, 19