

DEC 4 2 24 PM '96

Wanda R. Conday

REGISTER OF DEEDS

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

_____	Located In:	Corner Code #
(County)		
1. Public Land Survey	T 30NR 9W	I-3
	T ___ R ___	_____
	T ___ R ___	_____
	T ___ R ___	_____
2. Property Controlling in Section	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____
3. Miscellaneous Property in Sec.	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Terry B. Smith, in a field survey on Nov. 18, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3									●				
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

GLO Ran North between Sections 10 & 11,
set post common to sections 2,3,10, & 11
Y. Birch 9 N64W 20
Cedar 12 S64E 16

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Jan. 5, 1911 F. Church County Surveyor's Notes
Book 5 page 3
Feb. 19, 1988 - LCRC B. Jones
Jan. 23, 1951 Plat of Golden Beach - L. 2 of plats page 74
found 1/2" iron in intersection

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Antrim County Monument
10" Poplar N40W 59.90
10" Poplar N20E 34.78
U.P. S40W 46.75
conc. monument North 33.00

Ratified by Peer Group
in accordance with
PO 345.
Antrim County Chairman
Arthur L. Lennox
Arthur L. Lennox
Nov. 26, 1996

Signed by Terry B. Smith
Surveyor's Michigan License No. 25873



Date Dec. 3, 1996

96

002 332