NOV 1 6 1998

| | A. 345 ALPENA COL RAPPROVED 8/10 | 1998 Alpena (LAND CORNI | County Remonumentation Co ER RECORDATION CERTIFIC | |
|---|--|---|--|---|
| For corr | ners in | rining Requi | rement of Act 74, Mich. P.A. 1 | |
| | Alpena (County) | Located In: | Corner Code # | STATE OF MICHIGAN County of Alpena Recorded |
| 1. Publ | lic Land Survey | T <u>31N</u> R <u>6E</u> T <u>31N</u> R <u>5E</u> TR | A-2 V M-2 V | 08-20-1998 09:17:37 Kathy J. Matash REGISTER OF DEEDS |
| in S 3. Misc | perty Controlling ection cellaneous perty in Sec. | TR S T R S T R S T R | | Register of Deeds Stamp & File Number |
| | | orded Plat | | A B C D E F G H I J K L |
| i, <u>Danie</u> requirem were in instruction | IT, Kibbe , in a field tents of P.A. 74, Michig conformance with regula ons of the United State of a Court of Law and /o | an P.A. of 1970, the corner poir ations and rules therefore as requ s Department of the Interior, B r that the corner points mention | , 19 <u>98</u> do hereby state that under nts mentioned in lines 1 and 2 above uired in the current manual of survey ureau of Land Management or by a led in lines 3, 4 and 5 above were in veyors or by a Decree of a Court of | 1 2 6 5 4 3 2 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 |
| | ablished, re-established, | monumented, recovered, found | as expressed below: | 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36 |
| A. De: | scription of original m | onument and accessories an | d/or subsequent restoration: | |
| 1855: 1901: 1909: 1920: 1995: | County Survey by Ji W. Pine stump 30-S County Survey by Jo County Survey by Ji Survey by David B. | m H. LeRoy-set reddish gran 51 1/2-W87 ONBT/W. Pine os. W. McNeil-ran from corn m H. Leroy-ran from establis | stump 40-N71 3/4 E-96 NWT/Ce er established by Jim H. Leroy | crock around stone; referenced: edar Fence Post 8-S87 1/2 E 50 1/4 |
| B. De | scription of corner ev | idence found and/or method | applied in restoring or reestablis | hing corner: |
| 1998: | Remon. Survey by D of CL road to East. | aniel T. Kibbe-found 1/2" re | bar. 1' West of CL North-South | road. 1' South of CL road to West. 15' South |
| | | is compatible with county & position of the original corne | | ion is accepted as a careful and faithful |
| C. | Description of monu | ment for corner and accesso | ries established to perpetuate lo | cating the position of the corner: |
| 1998: | Referenced: Set tag ove FD DBG tag Set tag ove | ounty cap stamped to identify r nail in 15" Spruce N10W-9 pin Power pole N40E-69.70' r nail in 15" Spruce S50W-5 pin 4" Ash S60E-75.62' | • | , |
| | <i>)</i> _ | m | DANIEL T. KIBBE LAND SURVEYOR No. | |

Surveyor's Michigan License No. 37278

August 14, 1998