LIBER 2 PAGE 22

003317

RECORDED ALPENA COUNTY MI.

LAND	CORNER	RECO	RDAT	ION	CER	TIFIC	CAT	Ε
Filina	Requirem	ent of	Act 7	4. M	ich.	P.A.	197	٥

For corners in	Filing Requirement of Act 74, Mich. P.A. 1970	Jun 17 10 58 AM 196
Alpena (County)	Located In: Corner Code ##	Hathy Chilletonh.
1. Public Land Survey	T 31N R 07E T 31N R 06E T R	Jun 17 10 58 AM '96  *Kathy Chiliptonsh  REGISTER OF DEEDS
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	S T R S T R	gister of Deeds Stamp & File Number
4. Lot No, Re	corded Plat	- ABCDEFGHIJKL
•		2 - 6 5 4 3 2 1 - 3
		4 7 4 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Earl T. Lewis	in a field survey on April 10 19 <sup>96</sup>	5
do hereby certify that under require lines 1 and 2 above were in current manual of survey instruct Management or by a decree of a Cabove were in conformance with Court of Law; established, reexpressed below:	irements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned conformance with regulations and rules therefore as required in the citions of the United States Department of the Interior, Bureau of Land Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 the rules of the Michigan Board of Land Surveyors or by a Decree of a established, monumented, re-monumented, recovered, found as	6 18 17 16 15 14 13 7 8 19 20 21 22 23 24 9 10 30 29 28 27 26 25
NOTE: Not more than 4 cor on this certificate.	rners, all in the same town and range, may be recorded	12 31 32 33 34 35 36
, 233 3333 33	onument and accessories and/or subsequent restoration:	13
1840: Butler Ives 1883: W. Mirre 1914: J. McNeil 1958: G. Jerome & Co. 1995: David Guthrie, P.S.	Used a Hemlock 14" for corner, no witnesses given. Used corner, set 4" square cedar stake from GLO witness. at corner. No witnesses given. Used corner. No monumentation or witnesses given. Used corner. No monumentation or witnesses given. Used corner. Found nail. Set 1/2" iron rod. Witnesses g S 50° W 51.84' Utility Pole N 42° W 72.24' Utility Pole N 89° E 46.90' 6" Aspen S 81° E 64.34' 6" Spruce	
B. Description of corner evi	idence found and/or method applied in restoring or reestablishing Found 1/2* rerod w/cap #22435.	g corner:
SURVEY &		e al DENA COLINTY
_	P.A. 34	PROVED 5/5/1996
บบ ก 2 1096	beer Ap	PROVED ) / J / ' ' '

JUL 2 3 1996 ·

COMMISSION

P.A. 345 ALPENA COUNTY
PEER APPROVED 5/5/1996

ALL B. Car

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1996: Placed appropriately stamped Alpena County Remonumentation 3" aluminum cap on existing 1/2" rerod in monument box.

Witnesses given:

N 89 E 46.91' 6" Aspen (found tag) S 81 E 64.36' 6" Spruce (found tag) N 42 W 72.25' Utility Pole (found tag)

S 50° W 51.84' Utility Pole (found tag)

Date June 12, 1996

Signed by <b>Earl</b>	1. Lam
Sumevor's Michigan Licens	27.452

LEWIS
PROFESSIONAL
SURVEYOR
No.

WOFESSION !