1950 Albeita County Remonumentation Corner

-		
		5-26 6 4787 V
ATTO 13 17	16 13 B Com	Orne Co. 3 de la
COM	24 2 3 . 3	ن در مین ور پ
5 _R BEM	B 1 3 5 75	120
- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1		

For corners in

Private Claims

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

ALPEN	IA COL	INTY	MT
LIBER	1 2	ALE 3	77
Oct 11	10 38	AM	94
Maria	gra a. J.	جلتياه	J
REGIST	ER OF	DEED	S
		1 4 5	
			The state of the s

RECORDER

Alpena (County)	Located In:	Corner Code ##	уч 11 10 38 ДЛ уц
Public Land Survey	T <u>31N</u> R <u>7E</u> T R	H-9	REGISTER OF DEEDS
	T R T R		
Property Controlling in Section	S T R S T R		
Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number

June 9 Daniel T. Kibbe , in a field survey on ... do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5

above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as

expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration: 1855: G.L.O. Re-survey by Butler Ives - set post & referenced: Y. Pine 20 - N 84 E - 38

Y. Pine 15 - S 34 W - 85.

1892: County Survey by Wm. H. LeRoy - re-established old 1/4 corner, set cedar stake & reference 1910: County Survey by Jos. W. McNeil - referenced.

__ , Recorded Plat _

1930: County Survey by Wm. H. LeRoy - set 1"x36" iron pipe & referenced.

195 : Survey by Scott Engr. Co. - set "T" iron & referenced.

1961: Monument Witness Record by N.C. Caldwell - fnd "T" iron & referenced.

1963: MSHD Construction Plans - referenced "T" iron.

1964: Survey by James Scott - Airway Acres Plat

1968: MSHD - Re-witnessed 1/2" iron rod.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1976: Survey by David Guthrie - found mon. box.

1992: Survey by Earl Lewis - found mon. box & referenced.

1994: Found 1/2" iron bar in monument box.

This corner position is compatible with local surveys and agrees with MDOT records. This corner position is accepted as a careful and faithful perpetuation of the position of the original corner.

P.A. 345 ALPENA COUNTY	
DEER APPROVED Sept. 8,	1994
Del B. Lite	

Description of monument for corner and accessories		

1994: Placed 3" aluminum cap stamped to identify the corner over existing 1/2" iron rod in monument box.

Referenced:

N 38° E - center 5" steel fence post cut off flush with ground - 89.65'

N 37° W - center 5" steel fence post cut off flush with ground - 93.84'

S 65° E - center base of fence post at NE end clear vision fence - 201.85

S 70° W - center base of fence post at NW end clear vision fence - 20🗲

Signed by _

Date August

KIRRE . LAND SURVEYOR No.

DANIEL T

10

Surveyor's Michigan License No. _37278