LAND CORNER RECORDATION CERTIFICATE ,

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

1. PUBLIC LAND SURVEY 31 T. 31 N. R. 8 E. A-13 2. PROPERTY CONTROLL- N. S., R. E. ING IN SECTION T. S., R. W. 3. MISCELLANEOUS PROPERTY IN SECTION T. S., R. W. 4. LOT NO. RECORDED PLAT 5. PRIVATE CLAIMS REGISTER OF DEEDS STAMP AFILING NUMBER 1. Carl R. Johnson T. Ado hereby certify that under requirements of P.A. 74, Michigan P.A. of the corner points mentioned in lines 1 and 2 above were, in a field survey on February 12 Testablished, monumented, re-monumented, recovered or restored as expressed below and in conformance with regular and rules therefore as required in the current manual of survey instructions of the United States Department of the Induced Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines and 5 above were, in a field survey on Testablished or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, Decree of a Court of law: A. Description of original monument and accessories and/or subsequent restoration:	FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
3. MISCELLANEOUS PROPERTY IN SECTION, T	I. PUBLIC LAND SURVEY 31	T. 31 N. R. 8 E.	A-13	
3. MISCELLANEOUS PROPERTY IN SECTION, T	2. PROPERTY CONTROLL- ING IN SECTION	,T N E W.		
I,				
I,	4. LOT NO, REC	CORDED PLAT		
the corner points mentioned in lines 1 and 2 above were, in a field survey on <u>February 12</u> , 19.86, established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulant rules therefore as required in the current manual of survey instructions of the United States Department of the International Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines and 5 above were, in a field survey on	5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP A
	the corner points mentioned in re-established, monumented, re- and rules therefore as required Bureau of Land Management of and 5 above were, in a field sur- as expressed below and in confi- Decree of a Court of law:	lines I and 2 above were, in the current manual of sur r by a decree of a court of law vey on	a field survey on <u>February</u> restored as expressed below an vey instructions of the United v. Furthermore, that the corn 19, found, recovered, re Michigan State Board of Regis	7 12 , 19.86 , established in conformance with regular States Department of the Integral of th
	B. Description of corner evide	nce found and/or method ap	olied in restoring or re-establish	ing comer:
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:				
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:	Found corner in pla	ce from previous sur	vey	
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Found corner in place from previous survey				
	C. Description of monument !	or corner and accessories esta	blished to perpetuate locating t	he position of the corner:
	A-13			
Found corner in place from previous survey C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:	Found 2" nine in co	onc. and set cedar po	st	WHITE OF MICHINA
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-13 Found 2" pine in core, and set redar post	18" R. Pine N1°	OE 17.6'		
Found corner in place from previous survey C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-13 Found 2" pine in core, and set cedar post	*20" W. Pine S60	о́E 16.0'		JOHNSON &
Found corner in place from previous survey C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-13 Found 2" pine in core, and set cedar post			ਸ ਤ =	LAND 1
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-13 Found 2" pipe in conc. and set cedar post 18" R. Pine N1°W 27.0' 18" W. Pine N86°E 17.6' *20" W. Pine S60°E 16.0' LAND LAND LAND LAND	*old Witness Tree	9		NO NO
Found corner in place from previous survey C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-13 Found 2" pipe in conc. and set cedar post 18" R. Pine N1°W 27.0' 18" W. Pine N86°E 17.6' *20" W. Pine S60°E 16.0' **CARL R. JOHNSON ALAND SURVEYOR				% 30083 . 5 E
Found corner in place from previous survey C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-13 Found 2" pipe in conc. and set cedar post 18" R. Pine N1°W 27.0' 18" W. Pine N86°E 17.6' *20" W. Pine S60°E 16.0' **CARL R. JOHNSON ALAND LAND SURVEYOR	4	α ,	14	ANO SURVENIENT
Found corner in place from previous survey C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-13 Found 2" pipe in conc. and set cedar post 18" R. Pine N1°W 27.0' 18" W. Pine N86°E 17.6' *20" W. Pine S60°E 16.0' *old Witness Tree *old Witness Tree	and the second		DATE 2/2	J. J. W.
Found corner in place from previous survey C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-13 Found 2" pipe in conc. and set cedar post 18" R. Pine N1°W 27.0' 18" W. Pine N86°E 17.6' *20" W. Pine S60°E 16.0' *old Witness Tree *old Witness Tree	SIGNED BY CARCO		DATE	
Found corner in place from previous survey C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-13 Found 2" pipe in conc. and set cedar post 18" R. Pine N1°W 27.0' 18" W. Pine N86°E 17.6' *20" W. Pine S60°E 16.0' *cold Witness Tree	SURVEYOR'S MICHIGAN B	EGISTRATION NO3008	3	(GEAL)
Found corner in place from previous survey C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-13 Found 2" pipe in conc. and set cedar post 18" R. Pine N1°W 27.0' 18" W. Pine N86°E 17.6' *20" W. Pine S60°E 16.0' *old Witness Tree SURVEYOR'S MICHIGAN REGISTRATION NO. 30083				
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-13 Found 2" pipe in conc. and set cedar post 18" R. Pine N1°W 27.0' 18" W. Pine N86°E 17.6' *20" W. Pine S60°E 16.0' *old Witness Tree SIGNED BY DATE SURVEYORS MICHIGAN REGISTRATION NO. 30083 GEAL) FOR STATE AND UNITED STATES AGENCIES:	SIGNED BY	CHIEF OF SURVEY PARTY	DATE	
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-13 Found 2" pipe in conc. and set cedar post 18" R. Pine N1°W 27.0' 18" W. Pine N86°E 17.6' *20" W. Pine S60°E 16.0' *old Witness Tree SIGNED BY DATE SURVEYORS MICHIGAN REGISTRATION NO. 30083 GEAL) FOR STATE AND UNITED STATES AGENCIES:				
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-13 Found 2" pipe in conc. and set cedar post 18" R. Pine N1°W 27.0' 18" W. Pine N86°E 17.6' *20" W. Pine S60°E 16.0' *old Witness Tree *old Witness Tree DATE SURVEYORS MICHIGAN REGISTRATION NO. 30083 CHEEF OF SURVEY PARTY DATE CHIEF OF SURVEY PARTY DATE CHIEF OF SURVEY PARTY DATE		MICHIGAN REGISTERED	LAND EURVEYOR	(SEAL)
Found corner in place from previous survey C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-13 Found 2" pipe in conc. and set cedar post 18" R. Pine N1°W 27.0' 18" W. Pine N86°E 17.6' *20" W. Pine S60°E 16.0' *old Witness Tree *old Witness Tree No. 30083 SIGNED BY DATE CHIEF OF SURVEY PARTY APPROVED AND SIGNED BY DATE DATE DATE				
Found corner in place from previous survey C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-13 Found 2" pipe in conc. and set cedar post 18" R. Pine N1°W 27.0' 18" W. Pine N86°E 17.6' *20" W. Pine S60°E 16.0' *old Witness Tree No. SURVEYOR N	SUBALEAUS VICTUCAN D	FCISTRATION NO	Alm	ena Countv
Found corner in place from previous survey C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-13 Found 2" pipe in conc. and set cedar post 18" R. Pine Ni ^o W 27.0' 18" W. Pine N86 ^o E 17.6' *20" W. Pine S60 ^o E 16.0' *old Witness Tree SIGNED BY AVIOLATE AND SURVEYOR SURVEYOR'S MICHIGAN REGISTRATION NO. 30083 CHIEF OF SURVEY PARTY APPROVED AND SIGNED BY DATE CHIEF OF SURVEY PARTY DATE DATE	THE PERSON OF TH			· J