

Alpena County Remonumentation

LIBER

2 PAGE 08

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED ALPENA COUNTY MI.

For corners in			•	•		(h- 12	_		D 11	•			
λl	pena County	Located In:		Corner Code ##	1	Ĺ	ct 12	Z	13	M	'95	ļ		
1.	Public Land Survey	•	T 32N R 05E T R T R	C-11	,	Harty Children REGISTER OF DEEDS								
	Property Controlling in Section Miscellaneous Property in Sec.	s : s :	T R T R T R		Regi	CU 5759 Register of Deeds Stamp & File Number								
				1		A B	Ç D	E F	G	н	I J	ĸ	L	N
5.	Private Claims			Variable Marie Control of the Contro		2 5				Ţ	Ţ	Ŀ	^	_
	Earl T. Lewis	in a field c		0 , 19 95		3 - 7-	++-	+		10—	- - -	 	 	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:							29	21-29		22-	2:	,		3— 4— 5—
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.						11 12 31- 13	32	33		34-		<u> </u>	3	 6
A.	AUGUST 20, 1856: GLO	Surveyor, Jos		nd/or subsequent restorationst, no monumentation given		given:								

MARCH 04, 1974: Porter Survey, found 1/2" pipe, witnesses given: N 40° E 49.85' Black Ash, Due East 28.23' Fe. Corner

MAY 12 1894: County Surveyor W. LeRoy, set cedar stake, witnesses given:
B. Ash 4 S 62° E 26, Dead Pine 2 S 87° W 37, Cedar stake 5 West 50, Cedar stake 4 East 50 AUGUST 16, 1895: County Surveyor W. LeRoy, found cedar stake, witnesses given: Same as above. JUNE 16, 1915: County Surveyor W. LeRoy, found cedar stake, witnesses given: Same as above.

Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found nail with washer in intersection of Doran and Truax roads, and in line with an existing fence.

P.A. 345 ALPENA COUNT

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: 1995, Placed appropriately stamped Alpena County Remonumentation aluminum cap on set 1/2" x 24" rerod, which was set in place of existing nail.

Witnesses:

Signed by _______

Surveyor's Michigan License No.

N 35° E 50.85' 20" Ash

N 25° E 29.60' Power Pole S 85° E 34.53' 12" Ash N 85° E 27.30' Fe. Corner

S 35' E 57.75' 12" Poplar

S 40° W 61.27' 15" Red Pine

27452

October 8, 1995

LEWIS OFESSION

27452

OFESSION