## Survey a Femonumentation

## NOV 1 6 1998

1998 Alpena County R	Remonumentation	SECTION	00000 0440
	LAND (	CORNER RECORDATION CERT	Liber 00002 Page 0169
For corners in	Filing	Requirement of Act 74, Mich. P.	ii 1047E ii 1970
Alpena			STATE OF MICHIGAN
(County)	Located In:	Corner Code #	County of Alpena Recorded
1. Public Land Survey	TOOLE		10-08-1998 09:57:51
1. Public calld Survey	T <u>32NR 06</u> T <u>32NR 06</u>	5E A-9 7	Kathy J. Matash REGISTER OF DEEDS
	TR TR		CANACIES OF PEERS
2. Property Controlling	S TR_		
in Section 3. Miscellaneous	S TR_		
Property in Sec.	S IR S TR	<u> </u>	
			Register of Deeds Stamp & File Number
4. Lot No, Record	ded Plat		
5. Private Claims			A B C D E F G H I J K L
			2 6 5 5 1
I, Wayne T. Lewis	in a field survey on	5-19 , 19 <u>98</u> do hereby state that un	3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
requirements of r.M. 14, Michigan	1 P.A. OI 197U. THE COMET I	points mentioned in lines 1 and 2 above wen in the current manual of survey instructions of	
Other States Department of the in	iterior, Bureau or Land Man:	Bright of by a decree of a Cause of I am and	
Board of Land Surveyors or by recovered, found as expressed belo	a Decree of a Court of L	ere in conformance with the rules of the Michigan; established, re-established, monument	gan 7
			8 -19 -20 -21 -22 -23 -24
NOTE: Not more than 2 come on this certificate.	ers, all in the same town a	and range, may be recorded	9
			10 - 30 - 29 - 28 - 27 - 26 - 25
			12 31 32 34 35 36
A Description of original mon	nument and assessing	and the section of the section of	13
A. Description of original monument and accessories and/or subsequent restoration:     1857: GLO, Josiah Knauer, D.S found old post & witnessed			
1889: William H. Leroy, C.S found corner & witnessed 1892: William H. Leroy, C.S found corner			
1915: Joseph W. McNeil, C.S	3 set new stake in pla	ice of old one and set witness stake 50	links South
		à.	·
B. Description of corner evide	ence found and/or meth	od applied in restoring or reestablishing	
1998: Found 1/2" rerod in inte	ersection	as applied in restoring or reestablishing	corner,
This corner position is accepte	ed as a careful and faith	hful perpetuation of the position of the	Original corner
		perpendicular position of the	ongma corner,
			P.A. 345 ALPENA COUNTY
			PEER APPROVED \$\f\u00e4\forall
			Vel B. Cak
C. Description of monument for	or corner and accessorie	es established to perpetuate locating the	position of the corner:
1998: Placed 3" Alpena Cour	nty cap, stamped to iden	ntify the corner, on rerod, 6" below roa	d surface.
Witnesses:			WAYNE T.
S 45° E 40.85' Power Pole N 45° E 55.05' 6" Spruce	(found nail)		PROFESSIONAL SURVEYOR
N 30° W 74.65' 8" Spruce S 70° E 77.90' 5" Spruce			MO. 61
Opiuos			Management of the second
			STATE OF THE PROPERTY OF THE P
- 1		/	
Signed by	-7	Date	September 19, 1998
Surveyor's Michigan License No	o. <u>41922</u>		