## 1999 Alpena County Remonumentation

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	Filin	g Requirement of Act 74	, Mich. P.A. 1	970		•					
Alpena			1					درها درها در	V 0		
(County)	Located In:	Corner Code #				DC"	6248.		ىدائى مۇمىد	10	1
	•					i kämit∖	a top of the C	Javi Euro	7 # # 2		-
1. Public Land Survey	T <u>32NR (</u> T <u>33N</u> R ( TR_						JAN	2 1	2000	)	
2. Property Controlling in Section	TR S TR						SE	NC	Ì		
3. Miscellaneous Property in Sec.	S  K_ S TR_ S TR_				,		·_ '	•			
	. —				Regis	ter of C	eeds S	Stamp	& File	e Numb	er
4. Lot No, Reco	rded Plat			•							
5. Private Claims				1 A	В	C D	E F	G H	<u> </u>	JK	Ļ
				2	6	<del> </del>	┼-		-		- <u>1</u> -
I. Wayne T Lewis	in a field arman an	6.04		3	-	+		+			+
I, Wayne T. Lewis requirements of P.A. 74, Michiga	HILP A OT LY71) IDA COMA	r nointe montiese d'in line e 4		4	ー ウ 	 	<u> </u>	10	+	11-	12-
United States Department of the	ruies ineretore as required	f in the current manual of survey i	instructions of the	5			- -	<del>     </del>	+	<del> - -</del>	+
that the corner points mentioned Board of Land Surveyors or by recovered found as expressed by	1 (CI    ) ) PS .5 .4. 2 PCI ~ 2 PCV/6 14	MPA IN CORPANIANA A WALL AL		7	18 		16_ 	15	+	14	13- 
recovered, found as expressed be	elow:	Law, established, ra-establishe	a, monumented,	8	_19	20	21	22		23	24-
NOTE: Not more than 2 corr	ners, all in the same town	and range, may be recorded		9	1_						
on this certificate.		and range, may be recorded		10_	_30		28_	27-	_ _;	26	25-
				11	_ -			1-1-	┿	<del>                                     </del>	Ļ
				12	-31	32	33	34	<del> -</del> :	5	36 <u>—</u>
A. Description of original mo 1856: Josiah Knauer found i 1896: Wm. H. Leroy set Ced 1905: J. McNeil found cross 1918: J. McNeil found large 1962: G. Wozniak, MDOT St 1991: T. Fabis, P.S., found 1	cost and witnessed dar stake, 5" square, an line in East edge of roa Cedar stake, no monur urveyor, found 1-1/4" b	d witnessed ad, did not find stake, no mo mentation or witnesses give	numentation or	witnes	sses g	iven					
D. Danish H. J.						•					
B. Description of corner evid	lence found and/or meti	hod applied in restoring or re	establishing corr	ner:							
Found 1-1/4" pipe in mon. bo	x, 1 East of M-65 C/L.,	and 4' North of Kensa Roa	d C/L							•	
This comer position is accept	ed as a careful and fair	hful normatuation of the ana	:::			•	1				
росии и сосор.		mul perpetuation of the pos	ition of the origin	nai coi	rner.					-1.	
•			•	•	-	,		7			٠
				P.A. S	345 A	LPEŅ	A COL	INTY		e de la companya de l	
	•	•	PE	ER AF	PRC	VED.	9/1	1/99	P.		
		i		11		A.	<u>L</u>	,		•	
C. Description of monument f	or corner and accessori	es established to perpetuate	location the next	. tet	ei						
1999: Placed 3" Alpena Cour	nty Cap, stamped to ide	entify the corner, on 1/2" ren	od driven inside	pipe	T THE C	orner:	-0°7	North I	THE STATE OF THE S		,
Witnesses:								Ange de service	**************************************		
N 80° E 64.52' Se S 76° E 78.15' Po	et Chis. Notch in North wer Pole (Fd. Fabis Ta	End of 36" CMP				Ž.	* 1°	WAYN Lew	ÆT.	120	
	" in 55+57 Stationing S	tamped in Headwall			•		P	TOVES! SURVE NO	SIONA		The State of the S
, ** **	_					٩,		(1710) ( (1710) ( (17	18	Market St.	
9/		* .						· K. Massig	4 P.S. 3	•	
Signed by	- when		Date Nove	ember	24, ′	1999					
Surveyor's Michigan License N	o. <u>41922</u>										
		· <u></u>									