1999 Alpena County Remonumentation

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich PA 1970

For corners in	Fili	ing Requirement of Ac	t 74, Mich. P.A.	1970				
Alpena			1	، نرسیا			>.	: .
(County)	Located In:	Corner Code #		į k.	- 1 - v & No	garante a ta	البعاقا بالا	1
1. Public Land Survey	. T <u>32N</u> R T R		_		jan	2 j 200 0	. Comment	
	TR		<u>-</u>		SE(CTION		
2. Property Controlling in Section	S TR		-					2
3. Miscellaneous Property in Sec.	S TR S TR		- :			. ,		
	- <u></u> • •		<u> </u>	Re	gister of D	eeds Stamp	& File	Numbe
4. Lot No, Reco	orded Plat					• .	:	A. Stanford
5. Private Claims				A E	CDI	E F G H	I J	K L
				2 - {	;— 	-4- -	, — ½	
1 Marin T 1				3			++	-
I, Wayne T. Lewis requirements of P.A. 74, Michig	an P.A. of 1970, the com	per points mentioned in lines (Land 2 above upon	<u>⊾</u> 1 I		91	01,1	
conformance with regulations an	id rules therefore as require	ed in the current manual of sur	way instructions of th	<u>, 5 </u>				-
United States Department of the that the corner points mentione	d in lines 3. 4 and 5 above	• Were in conformance with the	rules of the Michiga	. 1	17	1615	<u>; </u>	13
Board of Land Surveyors or be recovered, found as expressed by	≫ a Decree of a Court o	of Law; established, re-estab	ished, monumented	d, 7			\dashv	
•				8 -13	20	2122 	23	24
NOTE: Not more than 2 cor on this certificate.	mers, all in the same tow	vn and range, may be record	ded	9 30 30				
		•		10 30	,		/— —26 	75
		•		11 12 31	32	333	35	36
A. Description of original m				13		ĬĬ		Ĭ
1896: Wm. H. Leroy found 1912: J. McNeil found com- 1962: G. Wozniak, MDOT S 1978: E. D. Farrier, P.S., fd 1989: E. T. Lewis, P.S., use	er set by Leroy, no witr Surveyor, found 1-1/4" 1" pipe in mon box, 1'	nesses given pipe in mon. box, 1.31' rt ' E. of M-65 C/L, recorded	. of M-65 C/L, and survey (L1, P734	d witnessed 4) & LCRC	(L1, P102)	, and witnes	ssed	
B Description of corner and	idanaa faund andlas —							
B. Description of corner evi Found 1-1/4" pipe in mon. b	ox. 1.2' East of M-65 (ethod appiled in restoring (:// and on Maple Lane F	or reestablishing o	orner:				
Fits both Poplar witnesses f	rom Farrier, but too ov	ergrown to use	.u. 0/L					
This corner position is accep	oted as a careful and fa	aithful perpetuation of the	position of the or	iginal corne	r.			
•				P.A. (345 ALPE	NA COUN	ITY	
				PEER A	PPROVE	D 9/14	199	
	,				01	B. L	~	
		•						1.5
C Description of manument	l far asmus and			•				
C. Description of monument					e corner:			
1999: Placed 3" Alpena Co	unty Cap, stamped to i	identify the corner, on 1/2	" rerod driven insi	ide pipe		and the second	3000gg	7 :
Witnesses:	W.O (O.11 B)				a.	WE OF IN	CAS	
	W Corner of Cable Ris Filed Notch in Angle Ir				3 C	MAYAW " PO		2
S 74°W 73.85' 1	0" Birch					/ Lewi Frofess		*
N 45° W 42.43′ S N 45° W 75.00′ S	Set 1/2" Rerod w/cap 9" Poplar				最 名	\$ SURVEY	70R }	6
	•				n in the second	3 A192	2 - "m. S	
		·			1	OF CCI	14 July 1973	, in
41	M. 1		**			ENDS I SUBSEINES	12314 A 1880	•
signed by	100	<u>~~</u>	Date	ovember 2	4, 1999			·
Surveyor's Mickigan License	No 4192	22		· .				



FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1985