NOV 1 6 1998

P.A. 345 ALPENA COUNTY

SECTION

PEER APPROVED SILVSY 1998 Alpena County Remonumentation Corner LAND CORNER RECORDATION CERTIFICATE Filling Requirement of Act 74, Mich. P.A. 1970Liber 00002 Page 0144

For corners in STATE OF MICHIGAN County of Alpena Corner Code # Located In: Alpena Recorded (County) 08-20-1998 09:18:12 Kathy J. Matash 1. Public Land Survey T_32N R7E REGISTER OF DEEDS T R 2. Property Controlling in Section S R 3. Miscellaneous S R Property in Sec. Register of Deeds Stamp & File Number

Ŧ.	Lot No.		_ ,	Recorded	Plat	 	 	<u></u>	
5.	Private	Claims .				 	 		

in a field survey on . March 17 , 19 <u>98</u> do hereby state that under I. Daniel T. Kibbe . requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.

1	I	S	D	- E - E	9	-					
2	ļ_,	l 6	5	₩,	ļ 4 —	<u> </u>	۱		<u>.</u>	<u> </u>	
3	ļ	<u> </u>		-			-	Щ)	_
4	٠.	 	 -19:		 	- 1	o	1	1	···-1	2 -
5		ļ		-	 						
6	1	e —		1	6	1	5	1	4	-1]]
7	<u> </u>		<u> </u>							 	_
8	1	ļ 9	20	2	 1	2	2	2	3	z	 5
9									-	-	Ļ
10	_3	0	29-	2	B	2	7	2	6	-2	 5
11		├		-		<u> </u>					-
12	 3	1	32-	3	3	3	4	3	5	—з	 6
13		L							L.,.		<u> </u>

A. Description of original monument and accessories and/or subsequent restoration:

GLO Survey by Josiah Knaver-set section corner post, no old work found; referenced: Hemlock 38-N57E-31 links 1857:

Hemlock 40-S44W-38 links

1892: County Survey by William H. LeRoy-found old corner stake; referenced: Hemlock stub 40-S44W-33 ONBT

Survey by Earl T. Lewis-set 1/2" rod; referenced: 15" Maple-S45W-59.1'/12" Maple-S20W-59,21' 1981:

P.Pole-N40E-55.40'

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Remon Survey by Daniel T. Kibbe-found 1/2" rebar. CL of road to the North. Fence to the south, 4.5' South of East-West road 1' below surface.

This corner postion is compatible with county & local surveys. This corner position is accepted as a careful and faithful perpetuation of the position of the original corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: C.

Placed 3" Alpena County cap stamped to identify the corner over 1/2" iron rod. 1998: Referenced:

Set tag in P.Pole-N42E-55.841

Found tag in face of 6" maple-\$26W-59.01"

Set tag in P.Pole-N37W-67.36' Set tag in fence post-S47E-45.65

an Signed by Surveyor's Michigan License No.

MICHIE TE OF DANIEL T. KIBBE LAND SURVEYOR No. 37 27

August 14, 1998 Date

OVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 REVISED OCT., 1995