DEC 0 3 1993

5. Private Claims

expressed below:

005685

1 PAGE 252 LIBER SEP 10

DOM Wipena County Remonumentation Corner

_____, Recorded Plat _

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Marieyo a foliator REGISTER OF DEEDS

For corners in Alpena (County)				
		Located In:	Corner Code ##	
1.	Public Land Survey	T 32N R 8E T R T R T R	C-8	
2.	Property Controlling in Section	S T R S T R		
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number

I David B. Guthrie in a field survey on August 16, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

3	_	В	C	D	<u> </u>	F	G	H	<u> </u>	K		N
;	2	6	_	5—		4	L	3_	_;	Ĭ		_
;	3	_	<u> </u>			L	<u> </u>	 .				
٠.	٠L	<u></u>		_	L	ļ	L.	 	1	ļ		2
,	5	Ĺ		Ĺ	<u>. </u>	Ĺ		Ĺ		L		_
,	<u>в</u>	 18	L,	[L.	B	L,	<u></u>				3—
	, [Ĭ		Ĺ		Ĺ		Ľ				
			Γ.	Ĭ	Γ,	Ţ	Ι,			Ž		
		19	T	:0— 	Γ		ľ	2— 	-2	J 		4
10	. [T	Τ.	1			<u> </u>					_
1		30 	1-	:9— 	Γ΄	8—	-2	/— I	-2	6— 	<u>2</u> 	5
1	Γ		Τ.		Ι.							_
13		3°1	 	i2 	-3	3	3	4 	3	5 	3	6
71	۱	+			·		···	 -		ļ		

- A. Description of original monument and accessories and/or subsequent restoration:
 - 1855: G.L.O re-survey by Josiah Knauer Set post and referenced: Cedar 5 N59W 10 / W. Birch 7 S37E 13.
 - 1888: County survey by Fred A. Rice Found G.L.O Corner 1894: County survey by Fred A. Rice Found G.L.O Corner 1903: County survey by Jos. McNeil Found G.L.O Corner and remains of both
 - N.B.T.S.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- 1993: Found 3" x 3" Cedar square stake (very old). No evidence of N.B.T.S.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1993: Set ½" x 24" iron rod with a 3" aluminum cap stamped <u>t</u>o identify the OF MICHIC

corner. Referenced: N70°E - 7" Cedar - 12.03 feet S25°E - 7" Ash - 5.51 feet S10°W - 6" Cedar - 10.61 feet S88°W - 6" Cedar - 9.45 feet

Signed by DDB. C	tele
Surveyor's Michigan License No.	22435