DEC 1 0 1993

Property in Sec.

5. Private Claims __

007740

1993	Algena County Ren	Remonu	monumentation		n	Corner		
	The Court of the Party of the P							_

_____ , Recorded Plat .


LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED	
ALPENA COME	MT

or comers in	•		
Alpena (County)	_ Located In:	Corner Code ##	DEC 7 9 21 AH '93
. Public Land Survey	T <u>32N</u> R <u>8E</u> T R T R	G-7	REGISTER OF DEEDS
Property Controlling in Section Miscellaneous	S T R S T R		

Register of Deeds Stamp & File Number

I, Daniel T. Kibbe , in a field survey on July 1	. 1993
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the cor	mer points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefor	
current manual of survey instructions of the United States Department of the Int	terior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentio	ned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyo	ors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, re-monument	recovered, found as
expressed below:	



NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
 - 1855: G.L.O. Re-survey by Josiah Knauer set post and referenced: Cedar 7 N57 1/2E 6 / Cedar $14^3 - S2 \frac{1}{4W} - 17$.
 - 1887: County survey by Fred A. Rice Found G.L.O. corner and referenced.

 - 1977: Survey by Duane MacNeill Set 1" pipe and referenced. 1981: Survey by Duane MacNeill Found 1" pipe and referenced.
 - 1993: Alpena County Road Commission- set 1/2" rebar in Monument Box after road construction.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- 1993: Found 1/2" rebar in Monument Box in the Center of Lacomb Road. This corner is very compatible with former county surveys. It is a reference for local surveys.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: 1993: Placed 3" aluminum cap stamped to identify the corner. Referenced:

\$27°W - 7" Cedar - 66.70 feet

S02°E - 8" Birch - 57.46 feet

N10°W - 6" Cedar - 45.98 feet N17°E - 7" Elm - 45.81 feet



Date November 24, 1993