WAY 1 6 1097

1996 ALPENA COUNTY REMONUMENTATION CORNER

LibiR

2 PAGE 43

| (3(3) | 9 / | Ġ | 11: | (- | 1 | ŀ, | ٠, | ٠, ١ |
|-------|-----|---|-----|-----|---|----|----|------|

LAND CORNER RECORDATION CERTIFICATE

| For corners in | Filing Requi | rement of Act 74, Mich. P.A. 1970 | O RECORDED ALPENA COUNTY MI. |
|---|--|--|--|
| Alpena (County) | Located in: | Corner Code # | ALPENA COURT I MIL. |
| 1. Public Land Survey | T <u>32N</u> R <u>8E</u> T R T R T R | Alpena Twp. | JUL 22 11 07 AM '96 **Pathyring dash REGISTER OF DEEDS |
| 2. Property Controlling in Section | ST R ST R | | REGISTER OF DEEDS |
| Miscellaneous Property in Section | ST R ST R | <u> </u> | legister of Deeds Stamp & File Number |
| Thomas L. Fabis do hereby certify that under req in lines 1 and 2 above were in c manual of survey instructions Management or by a decree of 5 above were in conformance Decree of a Court of Law; estal as expressed below; NOTE: Not more than 4 cor on this certificate. | onformance with regulations and of the United States Departr a Court of Law and/or that the cwith the rules of the Michigan Epilished, re-established, monumentary, all in the same town and | A. of 1970, the corner points mentioned rules therefore as required in the current ment of the Interior, Bureau of Land orner points mentioned in lines 3, 4 and soard of Professional Surveyors or by a inted, re-monumented, recovered, found d range, may be recorded | A B C D E F G H J K L M 2 6 5 4 3 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 |
| | | and/or subsequent restoration: uer - Set post & reference | ed. (Cadar 10 m |
| Corner tro | ee, Cedar 10 - N29W | $-2\frac{1}{2}$, Cedar 8 - S22W - 6). | · /oedal IO - |

B. Description of comer evidence found and/or method applied in restoring or reestablishing corner:

Made new witness: (Cedar stump 16 - S14°30'W - 33½ 1ks).

1996: Found 1/2" iron rod in centerline of Bloom Road. Old fence line going North from corner. Also, found concrete monument 50 feet North of corner on fence line.

The position of this corner is compatible with county and local surveys and is accepted as a careful and faithful perpetuation of the position of the original corner.

County Survey - Witness stumps had been removed to North side of road.

P.A. 345 ALPENA COUNTY
PEER APPROVED 5/14/90

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1996: Set 3" dia. aluminum cap, stamped to identify the corner, over the existing 1/2" iron rod.

Set tag #31591 in the following reestablished witnesses:

P. Pole - S38W - 72.10

10" Cedar - N30E - 33.05'

8" Balsam - N14W - 36.96'

6" Cedar - N36W - 43.10

THOMAS L. *

FABIS

LAND
SURVEYOR
No.
31591

ma July 17, 1996

1893: