

# LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>32</u> N. <u>9</u> E. <u>9</u> S., R. <u>9</u> E.	<u>A-1</u>
2. PROPERTY CONTROLLING IN SECTION <u>6</u>	, T. <u>32</u> N. <u>9</u> E. <u>9</u> S., R. <u>9</u> W.	<u>A1-1</u>
3. MISCELLANEOUS PROPERTY IN SECTION _____	, T. _____ N. _____ E. _____ S., R. _____ W.	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Kenneth J. Ostling do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on June 14, 1973, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_ 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:


- A-1 Found concrete monument at corner, previously established by Scott Engineering.
- A1-1 Found concrete monument in mound of stones - old 4" x 4" cedar post on ground - previously established by Scott Engineering.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

<p>A-1 Left Conc. Mon. in place Nail in 6" Cedar S16°E 6.2' Nail in 8" Cedar West 4.9'</p>	<p>A1-1 1/2" Rod in 4" Conc. Mon. Nail in 7" W. Birch N18°E 7.9' Nail in 6" W. Birch S20°W 4.85'</p>
--	--

SIGNED BY *Kenneth J. Ostling*  
 SURVEYOR'S MICHIGAN REGISTRATION NO. 10068

DATE 8/30/73



FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ CHIEF OF SURVEY PARTY DATE \_\_\_\_\_  
 APPROVED AND SIGNED BY \_\_\_\_\_ MICHIGAN REGISTERED LAND SURVEYOR DATE \_\_\_\_\_  
(SEAL)