SURVEY & REMONUMENTATION

MAY 1 0 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

KALKASKATA
RECEIVED MICHIGA 1994 DEC 23 AN 9:30
REG. OF DEEDS

corners in	in	orners	
------------	----	--------	--

Comera m		-	Viora Xa		
KALKASKA (County) 1994 REMONUMENT	Located In:	Corner Code ##	REG. OF DEFOS		
1994 REMONUMENT		F .			
Public Land Survey	T 28NR 8W	E-6			
	T R				
	TR				
	T R				
Property Controlling	S T R				
in Section	\$ T R				
Miscellaneous	S T R		Register of Deeds Stamp & File Number		
Propertý in Sec.	S T R				
	·				
Lot No , F	Recorded Plat		ABCDEFGHIJKL		
Private Claims					
		•	2 - 6 5 4 3 - 4 - 2 - 1 - 1 -		

EUGENE FARRIER, in a field survey on _ Nov. 12 rereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned nes 1 and 2 above were in conformance with regulations and rules therefore as required in the ent manual of survey instructions of the United States Department of the Interior, Bureau of Land ragement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 ve were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a irt of Law; established, re-established, monumented, re-monumented, recovered, found as ressed below:

FE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

6: Cor. common to Sec. 16 & 17, T28N-R8W, 150 GLO re-survey: set post, W. Pine 6", N64W, 29, Sugar 6", S40E, 9. 25-00, Unknown Co. Surv., fd stake and original accessories -27-79 & 6-26-80, A.L. Dragoo, fd cor. 1/2" pipe, w/accessories, Lib. Pq's 495, 496 & 563

21-83, Kalkaska Co Rd Comm., fd cor. 1/2" pipe, w/accessoried 26-86, E. Farrier, fd 1/2" pipe, w/accessories.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

6: Cor. common to Sec. 16 & 17, T28N-R8W, 1/4 cor. Sec. 16 ,T28N-R8W, fd 1/2" iron pipe raised with 1/2" iron & p #24594 "EDF", pulled both & replaced with 5/8" x 18" re-bar & brass p, 0.6' below gravel road. No GLO witnesses were found. 12-20-94 the Kalkaska Co. peer group approved the above monument as a reful and faithful reestablishment of the position of the original rner. Ratifled by Peer Group

P.A. 345 - 1990 Kalkaska County Chairman Emane

> TUGENE D. FARRIER

POFE SSIONAL HRVEYOR No. 24594

10

12

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

6: Cor. common to Sec. 16 & 17, T28N-R8W, 1/4 cor. Sec. 16, T28N-R8W, fd 1/2" iron pipe raised with 1/2" iron & p #24594 "EDF", pulled both & replaced with 5/8" x 18" re-bar & brass p, 0.6' below gravel road.

nail - 10" W. Pine, N47W - 61.20' nail - 12" W. Pine, N62E - 46.56'

nail - P. Pole, S14E - 100.90' nail - 12" W. Pine - S43W - 56.03'

rner falls in centerline Round Lk Rd.

evor's Mienigan License No.

Dale 12-22-94

FORM APPROVED BY MICHIGAN STATE BOARD

EVISED MAY 14, 1975 REVISED JAN., 1983